



SPOT REPAIR
15.8" VCP
1986

SPOT REPAIR
10.10" VCP
1986

Minor Lane
Plan to add
Private for
55' x 100' plus
872

Scale 1" = 200'



LAT. C-5, C-5-A, C-5-B, C-5-C, C-5-C-1, C-5-C-2
 COUNTRY ACRES IMPROVEMENT DISTRICT
 FLOYD B. DEVLIN, ENG. - UTILITY CONTRACTORS, INC.
 CONSTRUCTION DATE 1955 - BOOKED 1962

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
LAT C-5												
0+00	19.9	10.31	9.6	Exist. 0+00								
1+00	21.0	10.49	10.5									
	21.0	10.51	10.5	1+09 ^o	TAP	1+82 ^o		C24206	7105	School		11-30-71
2+00	20.2	10.73	9.5									
3+00	19.4	10.97	8.4									
	18.5	11.20	7.3	3+95 ^o	Stub E.							
LAT C-5-A												
0+00	19.0	11.09	7.9	Exist. 0+00								
1+00	20.0	11.95	8.1		TAP	1+16 ^o		C24205	2104	School		11-30-71
2+00	21.5	12.81	8.7		TAP	1+77.4		C45375	7105	Summittown		6-18-74
3+00	22.3	13.67	8.6		tap	2+31 ^o		C32703	1609	Summittown		6-7-72
	22.7	14.32 ^o	8.4	3+75 ^o	tap	3+14 ^o		C41886	1113	Summittown		10-26-73
4+00	22.8	14.55	8.3		tap	3+87 ^o		C42048	1114	Summittown		11-5-73
5+00	24.0	15.51	8.5		tap	4+98 ^o		C41887	1131	Summittown		10-26-73
6+00	24.8	16.47	8.3		tap	5+31 ^o		C44378	1125	Summittown		4-10-74
7+00	25.8	17.43	8.3		tap	5+87 ^o		C44379	1124	Summittown		4-10-74
	26.5	17.92	8.6	7+50 ^o	tap	6+44 ^o		C44380	1133	Summittown		4-10-74
8+00	27.2	18.39	8.8		tap	7+64 ^o		C44381	1137	Summittown		4-10-74
9+00	30.0	19.35	10.7		tap	8+31 ^o		C44394	1139	Summittown		4-10-74
10+00	31.7	20.31	11.4		tap	8+54 ^o		C44392	7105 W.			1-10-74
11+00	33.6	21.27	12.3		tap	10+86 ^o		C31925	11 St.			5-1-72
	34.0	21.52	12.5	11+25 ^o	tap	8+56 ^o		C44393	701 Co.			4-10-74
12+00	34.0	21.81	12.2		tap	11+35.9		C42047	1209	Summittown		11-5-73
13+00	34.0	22.21	11.8			14+19.4 ^o		C5685	1241	Summittown		2-30-86
14+00	34.0	22.61	11.4		tap	15+08.4		C28835	1247	Summittown		9-17-71
15+00	34.0	23.02	11.0	15+00 ^o	W.P.C.	17+83 ^o		C9213	1307	Summittown	see below	12-21-68
16+00	34.0	23.42	10.6			18+62 ^o		C4070	1317	Summittown		7-24-72
17+00	34.1	23.82	10.3			15+65 ^o		C32327	7105 W.			5-17-72
18+00	34.1	24.22	9.8			19+42 ^o		C4108	1305	Summittown		7-26-67
	34.2	24.52	9.7	18+75 ^o								
19+00	34.2	24.62	9.6									
20+00	34.2	25.02	9.2			17+27		C6064	1301	Summittown		4-25-78
21+00	34.2	25.42	8.8			21+00		C35761	1331	Summittown		11-2-72
22+00	34.2	25.82	8.4			21+88		C35812	1341	Summittown		11-6-72
	34.2	26.02	8.2	22+49 ^o		23+31.6		C50270	1347	Summittown		7-10-75
23+00	34.6	26.32	8.3									
	35.2	26.72	8.3	23+99 ^o	24+44			C12621	7115 W.			2-4-69
24+00	35.2	26.82	8.4									
25+00	35.0	27.22	7.8			24+53		C2444	7020	Summittown		6-17-71
	35.0	27.42	7.6	25+49 ^o								
26+00	35.0	27.72	7.3									
27+00	35.0	28.12	6.9			27+10 ^o		C29362	7014	Summittown		12-9-71
28+00	35.0	28.52	6.5			28+46 ^o		C43160	7007	W. 13th		1-24-74
29+00	35.0	28.92	6.1									
	35.0	29.00	5.7	29+20 ^o								

Rep-2000-02803-122960-AE Henning-4" SCH40 Tied to SDR35, Looked Like old Riser - ITWIN CO, 1022

LAT. C-5-B
 N.H. COVER 21.00 10.71 10.3 0+00
 L.H. COVER 20.00 11.05 9.0 0+85^o L.H.

Tap C44440-7109 N. 11th - 4-15-74 Gerald Thompson (top 8+83.2) on 133.2 N of MH 7+50.0
 Tap C44439-7515 N. 11th - 4-15-74 " (top 8+73.6) on 60.6 N of MH 8+13.0