

| CONSTRUCTION RECORD | | | | | | SERVICE RECORD | | | | | | |
|---------------------|-----------------|-------------------------|--------------|-----------------------------------|-----------------------|----------------|----------------------|------------------|--|--------------------|-------------------|------------|
| STATION | ELEVATION | | Depth | MANHOLE | 4-INCH "Y" BRANCHES | | No. of Permit | | House Number | | DATE OF PERMITS | |
| | Ground | Grade | | | North West | South East | North West | South East | North West | South East | North West | South East |
| Lat 55, S.W. I | | | | | | | | | | | | |
| Line 1 | | | | | | | | | | | | |
| 0+00 | | | | 0+00 Existing M.H. New 8" Clay | | | | | | | | |
| 1+49° | 142.5 | 131.55 | 9.9 | 1449° end existing line begin | | | | | | | | |
| 2+00° | 143.3 | 132.65 | 10.6 | | | | | | | | | |
| 3+00 | 144.0 | 132.91 in 132.83 out | 11.1 | 2+92° Line 1 = 8" 0+00 Line 2 | top 4+3440-50 3+54 | | C40627 | | 8708 University | | 8-15-73 | |
| 4+00 | 143.9 | 133.25 | 10.6 | | top 4+03 top 4+37 | top 4+33 | C40465 C40463 | C40626 | 3305 Tyler Bldg #2 8716 University | 8-8-73 | 8-15-73 | |
| 5+00 | 143.4 | 133.55 | 9.8 | | top 4+97 | top 5+50 | C40464 | C40625 | 3302 Tyler Bldg #2 8724 University | 8-8-73 | 8-15-73 | |
| 6+00 | 142.7 142.4 | 133.90 in 133.80 out | 8.8 8.4 | 5+80° | | | | | | | | |
| 7+00 | 143.6 | 134.26 | 9.3 | | | | | | | | | |
| 8+00 | 142.9 142.7 | 134.56 134.64 | 8.4 8.1 | 8+25° | | | | | 3305 Tyler Bldg #1 3305 Tyler Bldg #8 | | 8-8-73 | 8-8-73 |
| 9+00 | 143.4 143.7 | 134.86 135.00 | 8.5 8.7 | 9+47° w/6" Stub NE | | | C74606 | | 8715 W Maple | | 10-2-79 | |
| Line 2 | | | | | | | | | | | | |
| 0+00 | 144.0 | 133.13 | 10.9 | 0+00 Exst. = 2+92° Line 1 | top 0+57 | | C40628 | | 8708 University | | 8-15-73 | |
| 1+00 | 144.1 144.4 | 133.39 in 133.29 out | 10.8 11.1 | 0+78° = 0+00 Line 3 | top 1+67 | top 1+41 | 44-17278.7 C40467 | C40629 | 3305 Tyler Bldg #4 8632 University | 10-05-94 8-8-73 | 8-15-73 | |
| 2+00 | 144.1 144.7 | 133.53 in 133.73 out | 10.6 10.7 | 2+52° Line 2 = 0+00 Line 5 | | | | C40634 | 8624 University | | 8-15-73 | |
| 3+00 | 144.1 142.4 | 133.73 in 132.00 out | 10.4 8.4 | 3+87° Line 2 = 0+00 Line 4 | top 4+13.5 | | | C45952 | 8616 University | | 7-29-74 | |
| 4+00 | 142.1 | 134.02 | 8.1 | | 4+45.9 | | | C67221 | 351 University | | 7-6-78 | |
| 5+00 | 140.9 140.8 | 134.22 134.40 | 6.7 6.4 | 5+89° | 5+74.6 | 5+58.2 | C68802 | 5712 | 381 University | 37 University | 11-23-76 | 8-11-76 |
| Line 3 | | | | | | | | | | | | |
| 0+00 | 144.1 | 133.36 | 10.7 | 0+00 Exst. = 0+78° Line 3 | top 0+38 | | | C40468 | 3305 Tyler Bldg #4 | | 8-8-73 | |
| 1+00 | 143.8 144.00 | 133.89 133.94 | 9.9 10.1 | 1+091° w/6" Stub N & WNW | | | | C40466 C40472 | 3305 Tyler Bldg #3 3305 Tyler Bldg #6 | | 8-8-73 | 8-8-73 |
| Line 4 | | | | | | | | | | | | |
| 0+00 | 142.4 | 134.00 | 8.4 | 0+00 Exst. = 3+87° Line 2 | | | | | | | | |
| 1+00 | 141.3 142.0 | 134.21 134.16 | 7.1 7.1 | 1+25° end 8" Clay C.No dev | | | | | | | | |
| Line 5 | | | | | | | | | | | | |
| 0+00 | 144.7 | 133.71 | 11.0 | 0+00 Exst. = 2+52° Line 2 | | | | | | | | |
| 1+00 | 145.2 | 134.13 | 11.1 | | top 1+86 | | | C40469 | 341 3305 Tyler Bldg #5 | | 7-20-76 8-8-73 | |
| 2+00 | 144.0 143.8 | 134.53 134.67 | 9.5 9.1 | 2+35° | top 2+42 | top 2+76 | | C40471 C40470 | 3305 Tyler Bldg #5 3305 Tyler Bldg #5 | | 8-8-73 8-8-73 | |
| 3+00 | 143.8 | 134.93 | 8.9 | | | | | 3-64.4 | 57363 | 311 University | | 8-24-74 |
| 4+00 | 143.6 143.2 | 135.33 135.61 | 8.3 7.6 | 4+70° | top 4+33 | 4+60.8 | C40475 | C67503 | 3305 Tyler Bldg #7 8605 W Maple | | 8-8-73 | 7-25-78 |

44-17281-7 (330 S. Tyler) Apt Bldg #4 - 10-05-94 = 38' N of M.H. = +38