

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		DEPTH	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	GROUND	GRADE			North West	South East	North West	South East	North West	South East	North West	South East
SANITARY SEWER TO SERVE PHASE 2 OF PARK VISTA THIRD ADDITION												
0+00	235.44	218.53out	16.9	0+00 EXIST								
	235.44	218.65in	16.8									
1+00												
	235.04	218.72out	16.3	1+04.18	4" STUB SW 220.58	8" STUB E 220.6						
	235.04	218.84in	16.2									
2+00	234.00	218.95	15.0									
	234.27	218.98out	15.3	2+21.94	4" STUB NE 221.07	4" STUB S 220.85						
	234.27	219.07in	15.2									
3+00	233.10	219.23	13.9									
	233.16	219.31	13.8	3+42.20								
4+00												
	233.36	219.66	13.7	4+02.4	4" STUB NW 221.37		2000-02629	2000-01565	5240 Ashton	5308 E ASHTON ST	11-30-00	7-6-00
5+00	232.10	219.74	12.4									
	231.85	219.76	12.1	5+21.99	4" STUB W 220.65	8" STUB 220.33	2000-02001		5236 E ASHTON CT		9-11-00	
6+00	230.60	219.85	10.8									
					4" SCH 40 Predco 6+04.99 Saddle		2001-02038		5232 E Ashton Ct		8-15-01	
7+00	229.70	219.95	9.7									
	230.45	219.97	10.5	7+14.17	4" STUB NE 220.79	4" STUB SE 220.86	2001-01409	2000-02064	5315 E 49th CT N	5309 E 49th CT N	6-7-01	9-19-00
8+00	230.00	220.15	9.8		4" STUB SW 220.79							
	230.42	220.30	10.1	8+70.13	4" STUB SW 221.18	4" STUB SE 221.18	2001-00902		5245 E 49th ST N		4-16-01	
9+00	229.60	220.38	9.2									
	229.60	220.38	9.2		4" SCH 40 Predco 8+61.13 Saddle		2001-01649		5305 E 49th CT N			7-6-01
	230.57	220.49	10.1	9+38.49	4" STUB NW 221.36	8" STUB E 221.05	2001-01408		5248 E 49th ST N		6-7-01	
10+00	230.60	220.60	10.0									
					4" SCH 40 9+95.09			2000-01567		5302 E 49th ST N		7-6-00
10+82.17	229.10	220.75	8.4	PLUG								
LATERAL 380, SOUTHWEST INTERCEPTOR SEWER												
0+00 L-1	175.00	164.21 out	10.8	0+00 EXIST								
	175.00	164.31 in	10.7									
1+00	175.20	164.71	10.5									
2+00	175.40	165.11	10.3									
3+00	174.70	165.51	9.2									
	174.80	165.58 out	9.2	3+17.99								
	174.80	165.68 in	9.1									
4+00	175.80	166.00	9.8				2003-02797		8713 Oakridge		10-28-03	
5+00	176.80	166.40	10.4				2003-00607		8709 Oakridge		3-12-03	
	177.70	166.66 out	11.0	5+62.99 = 0+00 L-2								
	177.40	166.76 in	10.6		4" SCH 40 5+75.9'			2001-01648		8603 Oakridge Cir		7-6-01
6+00	177.00	166.90	10.1					2004-00443		8605 Oakridge		2-19-04
7+00	176.20	167.30	8.9									
	175.60	167.70 out	7.9	7+97.99								
	175.60	167.80 in	7.8									
8+00	178.60	168.18	10.4	8+92.07	4" STUB NE 168.51		2004-01585		8601 Oakridge		6-2-04	
0+00 L-2	177.70	166.76	10.9	0+00 = 5+62.99								
	177.50	167.20	10.3	0+50.25 CLEANOUT RISER				2004-02434		8710 Oakridge		9-9-04
LATERAL 320, SOUTHWEST INTERCEPTOR SEWER												
0+00 L-1	122.87	111.93	10.9	0+00 EXIST	4" SCH 40 DL 0+44 TAP	4" SCH 40 DL 0+18 TAP	2000-01741	2000-02548	5749 W Georgia	5748 W 42nd St S	7-28-00	11-20-00
1+00	124.70	114.56	10.1									
2+00	126.80	117.19	9.6		4" SCH 40 DL 0+80.5 TAP	4" SCH 40 DL 0+87 TAP	2000-02664	2000-02547	5737 Georgia	5736 W 42nd St S	9-19-00	11-20-00
	127.60	117.60 out	10.0	2+16.0	4" SCH 40 DL 2+34.0 TAP	4" SCH 40 DL 2+05.4 TAP	2001-01716	2000-01979	5711 Georgia	5710 W 42nd St S		9-6-00
	127.60	117.70 in	9.9		4" SCH 40 DL 2+83.0 TAP	4" SCH 40 DL 2+68.9 TAP	2001-01157	2000-02181	5701 Georgia	5700 W 42nd St S	5-12-01	10-4-00
3+00	129.00	118.52	10.5				2001-00460	2000-01453	5701 Georgia	5700 W 42nd St S	3-2-01	6-19-00
4+00	130.00	119.50	10.5		4" SCH 40 DL 3+15 TAP	4" SCH 40 DL 3+18.14 TAP	2000-02224	2000-01742	5623 W Georgia	5624 W 42nd St S	10-11-00	7-28-00
	130.80	119.80 out	11.0	4+31.14	4" SCH 40 DL 4+19.9 TAP		2001-02686	2000-01861	5611 W Georgia	5610 W 42nd St S	10-25-01	8-21-00
	130.80	119.90 in	10.9									
5+00	130.80	120.20	10.6	5+06.03 = 0+00 L-1A & 1B								
0+00 L-1A	130.80	120.30	10.5	0+00 = 5+06.03 L-1								
	130.60	120.60	10.0	0+74.5				2002-01917		4240 Gilda		7-12-02
								2003-02480		4232 Gilda		9-24-03
0+00 L-1B	130.80	120.30	10.5	0+00 = 5+06.03 L-1				2003-00874		4240 Gilda		4-3-03
	131.30	120.60	10.7	0+73.4				2003-00764		4254 Gilda		3-25-03
CONT. ON P-123												