

5232CPS1MME057 Quarterly PM Cheney Ozone Equipment Maintenance

Checklist

- 1 Cooling Water Skids: Grease Booster Pumps
- 2 Ozone Side Stream Pumps: Grease Pumps
- 3 Ozone Side Stream Pump Motors: Inspect Motor, Clean surfaces of excess dirt, grease and oil
- 4 Nitrogen Compressors: Clean Compressor Cooling Fins
- 5 Cooling Water Heat Exchanger Strainers: Switch Strainers, check and clean as needed
- 6 Ozone Degas Separators: Check floats and buttons