

5112A2R1EME002 Annual ASR PM River Intake MCC Inspection

DANGER HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

Use appropriate personal protective equipment-PPE-Follow safe electrical work practices-See NFPA 70E

1 Examine the interior and exterior of the MCC for moisture, oil, or other foreign material

2 Eliminate all foreign material and clean the MCC.

3 Clean the interior and exterior of the MCC with a vacuum cleaner. (Do not use compressed air)

4 Check the enclosure for damage that might reduce electrical clearances.

5 Examine the finish of the enclosure. Touch up the paint if necessary.

6 Replace any badly corroded or damaged enclosure parts.

7 Create a new work order for any needed and or repairs made during the PM work orde