

## 5420WTP1EME033 Quarterly MWTP PM Level Instrument Clean and Calibrate

### Checklist

- 1 Clean and Calibrate CP Clearwell level transducer in filter gallery
- 2 Clean and Calibrate CP Basin level transmitter
- 3 Clean and Calibrate East Plant Well Level Transmitter in Filter Gallery
- 4 Verify level and calibrate Ferric Bulk Tank Level Instrument
- 5 Clean Cable and Calibrate EP Well level transducer in filter gallery
- 6 Verify level and calibrate Ferric Day Tank Level Instrument
- 7 Verify Level and Calibrate Poly Tank level instruments
- 8 Verify and calibrate phosphate day tank level instrument.
- 9 Verify level and calibrate Ferric Bulk Tank level transmitter
- 10 Clean and Calibrate Contact Basin level instrument
- 11 Clean and Calibrate Central Plant Sludge Transfer level instrument (outside)