



FED. AID NO. CMQ-NO19(201)



Longitudinal joints shall be sawed and sealed with joint sealant. See Special Provisions for type.



MODIFIED CURB & GUTTER (COMBINED) (AE)				
STATION	STATION	SIDE	m	REMARKS
49+422.1	49+447.5	RT	25.4	21st STREET
49+422.1	49+448.3	LT	26.2	21st STREET
49+912.5	49+918.1	LT	5.6	21st STREET
49+946.9	49+950.6	LT	3.2	21st STREET - MEDIAN
49+950.0	49+975.6	LT	25	21st STREET - MEDIAN
50+119.6	50+122.1	LT	2.5	21st STREET - MEDIAN
50+179.4	50+200.0	LT	20.6	21st STREET
50+316.7	50+346.3	RT	29.6	21st STREET



HWS
Consulting Group Inc

Omaha Office
10844 Old Mill Rd., Ste 1
Omaha, NE 68154
Phone: (402) 333-5792
Fax: (402) 333-2248

Designed By:	BIWE	Checked By:	RJK
Drawn By:	HS, TS	Date:	3-25-2002
		Job No.	55-70-2003