



DIRT TRAIL REPAIR NOTE:
 Dished, rutted, and damaged sections of trail to be repaired and restored to a uniform, smooth surface. Contractor to ensure positive drainage over trail, with no low spots or areas of ponding on the trail.

QUANTITIES		
ITEM	QUANTITY	
CRUSHED CONCRETE PATH (4")	3,260 SF	
DIRT PATH (95% COMPACTION)	3,090 SF	