

12+25.00

1340

1340

1334.00
 1335.49

1330

1330

-40 -30 -20 -10 0 10 20 30 40

12+00.00

1340

1340

1334.00
 1335.64

1330

1330

-40 -30 -20 -10 0 10 20 30 40

11+75.00

1340

1340

1333.97
 1335.79

1330

1330

-40 -30 -20 -10 0 10 20 30 40

11+50.00

1340

1340

1333.93
 1335.72

1330

1330

-40 -30 -20 -10 0 10 20 30 40

11+25.00

1340

1340

1333.91
 1335.57

1330

1330

-40 -30 -20 -10 0 10 20 30 40

11+00.00

1340

1340

1334.06
 1335.43

1330

1330

-40 -30 -20 -10 0 10 20 30 40

10+75.00

1340

1340

1334.17
 1335.28

1330

1330

-40 -30 -20 -10 0 10 20 30 40

10+52.94

1340

1340

1334.18
 1335.15

1330

1330

-40 -30 -20 -10 0 10 20 30 40