

27+25.00

1350

1350

1340

1340

1341.04
1339.77

1330

1330

-40 -30 -20 -10 0 10 20 30 40

27+00.00

1350

1350

1340

1340

1341.38
1340.26

1330

1330

-40 -30 -20 -10 0 10 20 30 40

26+75.00

1350

1350

1340

1340

1341.70
1340.78

1340

1340

-40 -30 -20 -10 0 10 20 30 40

26+50.00

1350

1350

1340

1340

1342.02
1341.29

1340

1340

-40 -30 -20 -10 0 10 20 30 40

26+25.00

1350

1350

1340

1340

1342.34
1341.80

1340

1340

-40 -30 -20 -10 0 10 20 30 40

26+00.00

1350

1350

1340

1340

1342.68
1342.33

1340

1340

-40 -30 -20 -10 0 10 20 30 40

25+75.00

1350

1350

1340

1340

1343.09
1342.83

1340

1340

-40 -30 -20 -10 0 10 20 30 40