



CUT = 0  
LF = 0  
CF = 0  
MAN = 0

CUT = 50.0 CY  
MAN = 5.4 CY

Cut = 85.9 sq. ft.  
L.F. = 0  
C.F. = 0  
MAN. = 7.2

Total Cut = 189.2 cy  
LF = 26.2 cy  
CF = 7.5 cy  
Man. = 34.0 cy

Cut = 74.0 sq. ft.  
L.F. = 0  
C.F. = 8.1  
MAN. = 30.7

CUT = 139.2 CY  
L.F. = 7.3 CY  
LF = 26.2 CY  
MAN = 28.6 CY