



SITE 9

ROCK ROAD

INDIANAPOLIS

LONGFELLOW

614 S.
Longfellow

7808 E.
Indianapolis

Install 270 lf of 8"
Cured-in-Place Liner

MH # 5946-375
Approx depth = 8.5 ft

MH # 5946-384
Approx depth = 9.0 ft

228'

65'

270'

29'

274'

9-2



Aerial View



Television Inspection Master Report

9/6/2007
3:20:48PM

US Manhole: 5946-384 7808 E INDIANAPOLIS ST Date Insp: 1/17/2006 Basin: E01H
 DS Manhole: 5946-375 614 S LONGFELLOW LN Dir Televised: Upstream To Downstream

Pipe Information

Shape: Round Length Status: Project No.: H-171
 Dia/Ht Width: 8 0 Material: VCP Index:
 Length: 269.7 Slope: 1.852 Surface:

Inspection Information

Crew: 692 Percent Full: 10 Tape ID: 5951
 Weather: Sunny Purpose: TV Existing Line Counter Start: 0
 Surface Cond: Trees & Fences Flow: Normal Flow Counter Stop: 15.57

Obs. #	VTR Counter Svc. Address	Distance	Location	Description	Obs Rating	Obsrvd (gpm)	Est. (gpm)	Ratings Struct	Clean	Remain (gpm)
1		0.0	US Manhole	5946-384	1		0.000	0	0	0.000
2		3.0	Joint	Offset	3		0.010	20	0	0.010
3		6.0	Joint	Roots	4		0.010	10	25	0.010
4		11.0	Joint	Roots	4		0.010	10	25	0.010
5		14.0	Joint	Roots	3		0.008	5	8	0.008
6		16.0	Joint	Roots	2		0.004	2	4	0.004
7		19.0	Joint	Roots	4		0.010	10	25	0.010
8		22.0	Joint	Roots	3		0.008	5	8	0.008
9		25.0	Joint	Roots	2		0.004	2	4	0.004
10		28.0	Joint	Roots	3		0.008	5	8	0.008
11		30.0	South	Wye Service 4" Clay Wye Connection	2		0.000	0	0	0.000
				7808 E. Indianapolis – roots inside						
12		31.0	Joint	Roots	3		0.008	5	8	0.008
13		36.0	Joint	Roots	2		0.004	2	4	0.004
14		91.0	South	Wye Service 4" Clay Wye Connection	2		0.000	0	0	0.000
				7802 E. Indianapolis – roots inside						
15		120.0	Joint	Roots	4		0.010	10	25	0.010
16		130.0	Joint	Roots	3		0.008	5	8	0.008
17		139.0	Joint	Roots	4		0.010	10	25	0.010
18		150.0	South	Wye Service 4" Clay Wye Connection	3		0.000	2	0	0.000
				7720 E. Indianapolis - Full of Roots						
19		151.0	Joint	Roots	5		0.030	18	100	0.030
20		162.0	Joint	Roots	4		0.010	10	25	0.010
21		168.0	Joint	Roots	4		0.010	10	25	0.010
22		171.0	Joint	Roots	4		0.010	10	25	0.010
23		175.0	Joint	Roots	3		0.008	5	8	0.008
24		183.0	Joint	Roots	2		0.004	2	4	0.004
25		185.0	Joint	Roots	4		0.010	10	25	0.010
26		191.0	Joint	Roots	4		0.010	10	25	0.010
27		195.0	Joint	Roots	4		0.010	10	25	0.010

9-3

Television Inspection Master Report

9/6/2007
3:20:48PM

US Manhole: 5946-384 7808 E INDIANAPOLIS ST Date Insp: 1/17/2006 Basin: E01H
 DS Manhole: 5946-375 614 S LONGFELLOW LN Dir Televised: Upstream To Downstream

28	201.0	Joint	Roots	4	0.010	10	25	0.010
29	205.0	Joint	Roots	4	0.010	10	25	0.010
30	211.0	South	Wye Service 4" Clay Wye Connection	3	0.000	2	0	0.000
						7714 E. Indianapolis – Full of Roots		
31	213.0	Joint	Roots	3	0.008	5	8	0.008
32	222.0	Joint	Roots	4	0.010	10	25	0.010
33	223.0	Joint	Roots	2	0.004	2	4	0.004
34	225.0	Joint	Roots	4	0.010	10	25	0.010
35	227.0	Joint	Roots	3	0.008	5	8	0.008
36	237.0	Joint	Roots	3	0.008	5	8	0.008
37	238.0	Joint	Roots	2	0.004	2	4	0.004
38	251.0	Joint	Roots	4	0.010	10	25	0.010
39	253.0	Joint	Roots	4	0.010	10	25	0.010
40	259.0	Joint	Roots	4	0.010	10	25	0.010
41	264.0	Joint	Roots	3	0.008	5	8	0.008
42	265.0	Camera Lens Submerged		5	0.000	0	0	0.000
43	268.0	Camera Lens Emerged		1	0.000	0	0	0.000
44	269.0	DS Manhole	5946-375	1	0.000	0	0	0.000

(pipe does dip downward a little outside of the DS manhole wall, but we will line without a repair)