



W SCHOOL ST

N BROWNTHRUSH LN

N REDBARN LN

N WOODCHUCK LN

N CHICKADEE LN

869

865

859

839

843

840

Television Inspection Master Report

8/10/2010

9:20 AM

US Structure: 4948-016 840 N WOODCHUCK ST Date Insp: 6/11/2010 Basin: W06A
 DS Structure: 4948-015 869 N REDBARN ST Dir Televised: Downstream To Upstream

Pipe Information

Project No. : J-183 Dia/Ht: 15 Material: VCP Length: 422.9 Slope: 0.003
 Crew: 694 Tape ID: DVD #0583

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Ratings Struct	Clean	Remain (gpm)
1		0.0		4948-015 DS Manhole / TV against the flow						
2		2.0		Crack-Horizontal	3		0.004	5	0	0.004
3		12.8	North	Break-In Conn	1		0.001	0	0	0.001
869 NORTH REDBARN										
4		26.2		Crack-Horizontal	3		0.004	5	0	0.004
5		28.9		Crack-Horizontal	3		0.004	5	0	0.004
6		31.6		Crack-Horizontal	3		0.004	5	0	0.004
7		34.8		Crack-Horizontal	3		0.004	5	0	0.004
8		37.7		Crack-Horizontal	3		0.004	5	0	0.004
9		45.3		Crack-Horizontal	3		0.004	5	0	0.004
10		62.2		Crack-Horizontal	3		0.004	5	0	0.004
11		68.6		Crack-Horizontal	3		0.004	5	0	0.004
12		71.3		Crack-Horizontal	3		0.004	5	0	0.004
13		77.8		Crack-Horizontal	3		0.004	5	0	0.004
14		83.1		Crack-Horizontal	3		0.004	5	0	0.004
15		86.5		Crack-Horizontal	3		0.004	5	0	0.004
16		88.9	North	Wye Service	1		0.000	0	0	0.000
869 NORTH REDBARN / active?										
17		150.8		Crack-Horizontal	3		0.004	5	0	0.004
18		153.3	South	Break-In Conn	1		0.001	0	0	0.001
839 NORTH WOODCHUCK										
19		156.5		Crack-Horizontal	3		0.004	5	0	0.004
20		171.8	North	Wye Service	1		0.000	0	0	0.000
865 NORTH REDBARN / abandoned?										
21		176.8		Crack-Horizontal	2		0.002	2	0	0.002
22		179.6		Crack-Horizontal	3		0.004	5	0	0.004
23		189.4		Crack-Horizontal	3		0.004	5	0	0.004
24		194.7		Crack-Horizontal	3		0.004	5	0	0.004
25		203.5		Crack-Horizontal	3		0.004	5	0	0.004
26		206.7		Crack-Horizontal	3		0.004	5	0	0.004
27		209.7		Crack-Horizontal	3		0.004	5	0	0.004
28		212.8		Crack-Horizontal	3		0.004	5	0	0.004
29		215.7		Crack-Horizontal	3		0.004	5	0	0.004
30		218.8		Crack-Horizontal	3		0.004	5	0	0.004
31		222.4	North	Break-In Conn	5		0.010	400	0	0.010
859 NORTH REDBARN / roots										

Television Inspection Master Report

8/10/2010

9:20 AM

US Structure:	4948-016	840 N WOODCHUCK ST	Date Insp:	6/11/2010	Basin:	W06A
DS Structure:	4948-015	869 N REDBARN ST	Dir Televised:	Downstream To Upstream		
32	270.1		Crack-Horizontal	3	0.004	5 0 0.004
33	273.7		Crack-Horizontal	3	0.004	5 0 0.004
34	276.9		Crack-Horizontal	3	0.004	5 0 0.004
35	279.6		Crack-Horizontal	3	0.004	5 0 0.004
36	281.6		Crack-Horizontal	3	0.004	5 0 0.004
37	284.5		Crack-Horizontal	3	0.004	5 0 0.004
38	287.2		Crack-Horizontal	3	0.004	5 0 0.004
39	290.5		Crack-Horizontal	3	0.004	5 0 0.004
40	293.6		Crack-Horizontal	3	0.004	5 0 0.004
41	296.8		Crack-Horizontal	3	0.004	5 0 0.004
42	302.6		Crack-Horizontal	3	0.004	5 0 0.004
43	305.8		Crack-Horizontal	3	0.004	5 0 0.004
44	308.8		Crack-Horizontal	3	0.004	5 0 0.004
45	311.6		Crack-Horizontal	3	0.004	5 0 0.004
46	318.2	North	Wye Service	3	0.000	2 0 0.000
843 NORTH REDBARN / appears abandoned?						
47	325.1	Crown	Break-In Conn	3	0.004	2 0 0.004
843 NORTH REDBARN						
48	330.8		Crack-Horizontal	3	0.004	5 0 0.004
49	334.8		Crack-Horizontal	3	0.004	5 0 0.004
50	337.5		Crack-Horizontal	3	0.004	5 0 0.004
51	340.5		Crack-Horizontal	3	0.004	5 0 0.004
52	343.6		Crack-Horizontal	3	0.004	5 0 0.004
53	346.6		Crack-Horizontal	3	0.004	5 0 0.004
54	349.1		Crack-Horizontal	3	0.004	5 0 0.004
55	352.4		Crack-Horizontal	3	0.004	5 0 0.004
56	356.0		Crack-Horizontal	3	0.004	5 0 0.004
57	358.9		Crack-Horizontal	3	0.004	5 0 0.004
58	361.8		Crack-Horizontal	3	0.004	5 0 0.004
59	365.1		Crack-Horizontal	3	0.004	5 0 0.004
60	367.3		Crack-Horizontal	3	0.004	5 0 0.004
61	370.1		Crack-Horizontal	3	0.004	5 0 0.004
62	373.7		Crack-Horizontal	3	0.004	5 0 0.004
63	376.3		Crack-Horizontal	3	0.004	5 0 0.004
64	379.8		Crack-Horizontal	3	0.004	5 0 0.004
65	382.2		Crack-Horizontal	3	0.004	5 0 0.004
66	385.5		Crack-Horizontal	3	0.004	5 0 0.004
67	388.4		Crack-Horizontal	3	0.004	5 0 0.004
68	391.4		Crack-Horizontal	3	0.004	5 0 0.004
69	397.8	North	Wye Service	1	0.000	0 0 0.000
843 NORTH REDBARN / appears abandoned?						
70	401.8		Crack-Horizontal	3	0.004	5 0 0.004
71	404.4		Crack-Horizontal	3	0.004	5 0 0.004
72	407.7		Crack-Horizontal	3	0.004	5 0 0.004
73	410.6		Crack-Horizontal	3	0.004	5 0 0.004
74	413.5		Crack-Horizontal	3	0.004	5 0 0.004
75	416.6		Crack-Horizontal	3	0.004	5 0 0.004
76	423.1		US Manhole / 4948-016	1	0.000	0 0 0.000