



SITE 4

Estimated 11 Service Reconnections (4")
 Estimated 1 Curb Inlet Protection

N PEARCE AVE

N CARLOS AVE

1128

1125

1104

1103

535

510

W 10TH ST N

N



US Structure: 5448-535 1128 N PEARCE AVE Date Insp: 4/15/2010 Basin: C03E
 DS Structure: 5448-510 1104 N PEARCE ST Dir Televised: Upstream To Downstream

Pipe Information
 Project No.: B-234 Dia: 8 Material: VCP Length: 328.4 Slope: 0.001 DVD #0569

Obs. #	VTR Counter	Distance	Location	Description	Rating	Ratings			
						Obsrvd (gpm)	Est. (gpm)	Struct Clean	Remain (gpm)
1		0.0		5448-535 US Manhole (manhole has a slotted lid that lets sand & water into the main)					
2		15.1		Sealed Off Wye	1	0.000	0	0	0.000
3		16.1		Crack-Radial	2	0.002	2	0	0.002
4		21.0		Crack-Radial	3	0.004	5	0	0.004
5		25.5		Sealed Off Wye	1	0.000	0	0	0.000
6		26.6		Crack-Radial	2	0.002	2	0	0.002
7		28.9		Crack-Radial	3	0.004	5	0	0.004
8		31.3		Crack-Radial	1	0.001	1	0	0.001
9		40.0		Wye Service / cracked	2	0.000	0	0	0.000
10		41.1		Crack-Radial	2	0.002	2	0	0.002
11		42.6		Wye Service	1	0.000	0	0	0.000
12		43.6		Crack-Radial	3	0.004	5	0	0.004
13		55.5		Crack-Radial	3	0.004	5	0	0.004
14		58.2		Crack-Radial	2	0.002	2	0	0.002
15		65.2		Wye Service	1	0.000	0	0	0.000
16		67.1		Sealed Off Wye	1	0.000	0	0	0.000
17		68.3		Crack-Radial	2	0.002	2	0	0.002
18		70.9		Crack-Radial	2	0.002	2	0	0.002
19		85.7		Crack-Radial	3	0.004	5	0	0.004
20		88.4		Crack-Radial	1	0.001	1	0	0.001
21		91.1		Crack-Radial	2	0.002	2	0	0.002
22		92.3		Sealed Off Wye	1	0.000	0	0	0.000
23		94.9		Wye Service	1	0.000	0	0	0.000
24		95.9		Crack-Radial	2	0.002	2	0	0.002
25		98.4		Observation Hole	1	0.000	0	0	0.000
26		116.1		Crack-Radial	2	0.002	2	0	0.002
27		118.1		Crack-Radial	2	0.002	2	0	0.002
28		119.8		Wye Service	1	0.000	0	0	0.000
29		122.1		1116 N PEARCE					
30		123.0		(broken down) Wye Service	5	0.000	400	0	0.000
31		128.2		Crack-Radial	3	0.004	5	0	0.004
32		130.6		Crack-Radial	3	0.004	5	0	0.004
33		135.8		Crack-Radial	1	0.001	1	0	0.001
34		143.3		Crack-Horizontal	2	0.002	2	0	0.002
35		147.4		Crack-Horizontal	1	0.001	1	0	0.001
36		148.2		Sealed Off Wye	1	0.000	0	0	0.000
37		150.0		Crack-Radial	2	0.002	2	0	0.002
				Sealed Off Wye	1	0.000	0	0	0.000

US Structure: 5448-535 1128 N PEARCE AVE Date Insp: 4/15/2010 Basin: C03E
 DS Structure: 5448-510 1104 N PEARCE ST Dir Televised: Upstream To Downstream

38	155.9		Crack-Radial	1	0.001	1	0	0.001
39	168.0		Crack-Radial	1	0.001	1	0	0.001
40	170.7		Crack-Radial	2	0.002	2	0	0.002
41	175.0		Sealed Off Wye	1	0.000	0	0	0.000
42	175.5		Mat. Chngs to PVC (or sleeve repair)	0	0.000	0	0	0.000
43	177.9	1111 N CARLOS	Break-In Conn	1	0.001	0	0	0.001
44	178.4		Mat. Chngs to VCP	5	0.000	0	0	0.000
45	179.4	Broken Pipe / hole in pipe at end of repair		4	0.030	78	0	0.030
46	183.3		Crack-Radial	3	0.004	5	0	0.004
47	185.7		Crack-Radial	2	0.002	2	0	0.002
48	188.4		Crack-Radial	2	0.002	2	0	0.002
49	193.3		Crack-Radial	1	0.001	1	0	0.001
50	202.3	1112 N PEARCE	Wye Service	1	0.000	0	0	0.000
51	208.2		Crack-Radial	2	0.002	2	0	0.002
52	209.1		Observation Hole	1	0.000	0	0	0.000
53	210.8		Crack-Radial	3	0.004	5	0	0.004
54	212.7	1112 N PEARCE	Break-In Conn	1	0.001	0	0	0.001
55	213.1		Crack-Radial	2	0.002	2	0	0.002
56	217.4	1107 N CARLOS	Wye Service	1	0.000	0	0	0.000
57	218.4		Crack-Radial	1	0.001	1	0	0.001
58	220.7		Crack-Radial	3	0.004	5	0	0.004
59	223.3		Crack-Radial	1	0.001	1	0	0.001
60	228.3		Crack-Radial	2	0.002	2	0	0.002
61	235.6		Crack-Radial	2	0.002	2	0	0.002
62	238.3		Crack-Radial	1	0.001	1	0	0.001
63	239.8		Sealed Off Wye	1	0.000	0	0	0.000
64	242.4		Sealed Off Wye	1	0.000	0	0	0.000
65	243.4		Crack-Radial	2	0.002	2	0	0.002
66	250.7		Crack-Radial	3	0.004	5	0	0.004
67	253.3		Crack-Radial	2	0.002	2	0	0.002
68	255.8		Crack-Radial	3	0.004	5	0	0.004
69	260.7		Crack-Radial	1	0.001	1	0	0.001
70	269.7		Sealed Off Wye	1	0.000	0	0	0.000
71	272.4	1103 N CARLOS	Wye Service	1	0.000	0	0	0.000
72	284.9		Sealed Off Wye	1	0.000	0	0	0.000
73	285.6		Roots	2	0.004	2	4	0.004
74	286.1		Crack-Radial	2	0.002	2	0	0.002
75	287.3		Sealed Off Wye	1	0.000	0	0	0.000
76	288.1		Roots	2	0.004	2	4	0.004
77	290.4		Roots	2	0.004	2	4	0.004
78	292.9		Roots	1	0.002	1	1	0.002

US Structure: 5448-535 **1128 N PEARCE AVE** **Date Insp:** 4/15/2010 **Basin:** C03E
DS Structure: 5448-510 **1104 N PEARCE ST** **Dir Televised:** Upstream To Downstream

79	293.4	Crack-Radial	2	0.002	2	0	0.002
80	295.3	Roots	1	0.002	1	1	0.002
81	297.9	Roots	1	0.002	1	1	0.002
82	300.4	Roots	1	0.002	1	1	0.002
83	302.9	Roots	1	0.002	1	1	0.002
84	310.3	Crack-Radial	3	0.004	5	0	0.004
95	322.3	5448-510 DS Manhole	1	0.000	0	0	0.000

Pipe has lots of roots that are not listed on the log.

SAG RECORDS:

85	39.5	Sag	2	0.000	2	0	0.000
86	40.6	Sag	4	0.000	10	0	0.000
87	73.5	Sag	1	0.000	1	0	0.000
88	73.5	Sag	1	0.000	1	0	0.000
89	148.6	Sag	4	0.000	10	0	0.000
90	148.6	Sag	5	0.000	25	0	0.000
91	166.4	Sag	1	0.000	1	0	0.000
92	171.9	Sag	4	0.000	10	0	0.000
93	180.6	Sag	1	0.000	1	0	0.000
94	183.7	Sag	1	0.000	1	0	0.000

(some sags over the lens, others not as bad)