



SITE 1

Sheet 3 of 22







Video Inspection Master Report

9/10/2012

7:33 AM

US Structure: 5546-543 1315 E LINCOLN ST Date Insp: 9/20/2011 Basin: C02A
 DS Structure: 5546-542 1217 S LULU ST Dir Televised: Upstream To Downstream

Pipe Information

Project No. : D-108 Dia: 8 Material: VCP Length: 207.8 Slope: 0.400

Obs.VTRRatings

#	Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Struct	Clean	Remain (gpm)
1		0.0		US Manhole 5546-543	1		0.000	0	0	0.000
2		9.3		Broken Pipe	3		0.010	60	0	0.010
3		19.3	1315 EAST LINCOLN	4" Break-In Conn	1		0.001	0	0	0.001
4		21.1		Sealed Off Wye	1		0.000	0	0	0.000
5		22.5		PR Starts - Mat. Chngs to PVC	1		0.000	0	0	0.000
6		25.0	1317 EAST LINCOLN	PVC Break-In Conn	1		0.001	0	0	0.001
		40.0		Gapped joint in existing PVC repair						
7		50.2		PVC, tap facing east (vacant lot?) Break-In Conn	1		0.001	0	0	0.001
8		52.2	1301 EAST LINCOLN	PVC Break-In Conn	1		0.001	0	0	0.001
9		54.4	1205 SOUTH LULU	PVC Break-In Conn	1		0.001	0	0	0.001
10		57.3		PR Ends - Mat. Chngs back to VCP	1		0.000	0	0	0.000
11		76.3		Sealed Off Wye	1		0.000	0	0	0.000
12		79.0	1205 SOUTH LULU	Wye Service	1		0.000	0	0	0.000
13		83.2		Broken Pipe	2		0.008	44	0	0.008
14		93.9		Broken Pipe	3		0.010	60	0	0.010
15		95.4	(to vacant lot? Not sealed at main)	Break-In Conn	1		0.001	0	0	0.001
16		98.9		Broken Pipe	2		0.008	44	0	0.008
17		102.7		Sealed Off Wye	1		0.000	0	0	0.000
18		110.4	1210 SOUTH PATTIE	Break-In Conn	1		0.001	0	0	0.001
19		126.4		Sealed Off Wye	3		0.000	0	0	0.000
20		127.8		Broken Pipe	3		0.010	60	0	0.010
21		128.9	(seal broken, lets in dirt)	Sealed Off Wye	3		0.000	0	0	0.000
22		139.2	1211 SOUTH LULU	Break-In Conn	1		0.001	0	0	0.001
23		141.3	Pipe missing / cavity outside of main	Broken Pipe	4		0.030	78	0	0.030
24		150.9		Crack-Radial	3		0.004	5	0	0.004
25		152.6	1214 SOUTH PATTIE	PVC Break-In Conn	1		0.001	0	0	0.001
26		155.5	(seal broken, lets in dirt)	Sealed Off Wye	1		0.000	0	0	0.000
27		156.6		Broken Pipe	3		0.010	60	0	0.010
28		159.6		Broken Pipe	2		0.008	44	0	0.008
29		161.4		Broken Pipe	3		0.010	60	0	0.010
30		164.7		Debris	3		0.000	0	0	0.000
31		166.9		Broken Pipe	3		0.010	60	0	0.010
32		172.1		Broken Pipe	3		0.010	60	0	0.010
33		185.1		Broken Pipe	3		0.010	60	0	0.010
34		186.5	1220 SOUTH PATTIE	PVC Break-In Conn	1		0.001	0	0	0.001
35		188.0	1217 SOUTH LULU	Break-In Conn	1		0.001	0	0	0.001
36		193.1		Broken Pipe	3		0.010	60	0	0.010
37		209.8		5546-542 DS Manhole	1					<i>Pipe has poor grade</i>



Video Inspection Master Report

9/10/2012

7:33 AM

US Structure: 5546-542 1217 S LULU ST Date Insp: 9/20/2011 Basin: C02A
 DS Structure: 5546-541 1235 S LULU AVE Dir Televised: Upstream To Downstream

Pipe Information

Shape: Round Length Status: Project No. : D-108
 Dia/Ht: 8 Material: VCP Index:
 Length: 209.2 Slope: 0.002 Surface:

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Ratings			Remain (gpm)
							Est. (gpm)	Struct	Clean	
1		0.0		5546-542 US Manhole	1	0.000	0	0	0.000	
2		6.3	(hole in crown / cavity)	Broken Pipe	4	0.030	78	0	0.030	
3		9.0		Broken Pipe	3	0.010	60	0	0.010	
4		20.8	(seal broken, lets in dirt)	Sealed Off Wye	3	0.000	0	0	0.000	
5		23.4		Sealed Off Wye	1	0.000	0	0	0.000	
6		41.5	1224 SOUTH PATTIE	PVC 4" Break-In Conn	1	0.001	0	0	0.001	
7		41.8	1221 SOUTH LULU	Break-In Conn	1	0.001	0	0	0.001	
8		45.9		Crack-Radial	2	0.002	2	0	0.002	
9		47.1	1224 SOUTH PATTIE	Wye Service	3	0.000	2	0	0.000	
10		48.2		Crack-Radial	3	0.004	5	0	0.004	
11		49.7	(seal broken, lets in dirt)	Sealed Off Wye	4	0.000	0	0	0.000	
12		73.2		Sealed Off Wye	1	0.000	0	0	0.000	
13		75.7		Sealed Off Wye	1	0.000	0	0	0.000	
14		79.7	(pipe missing / cavity outside main)	Broken Pipe	3	0.010	60	0	0.010	
15		91.8	1225 SOUTH LULU	Break-In Conn	1	0.001	0	0	0.001	
16		99.5	1226 SOUTH PATTIE	Wye Service	2	0.000	0	0	0.000	
17		102.1	(seal broken, lets in dirt)	Sealed Off Wye	4	0.000	0	0	0.000	
18		125.9		Sealed Off Wye	3	0.000	0	0	0.000	
19		127.4		Broken Pipe	4	0.030	78	0	0.030	
20		128.2	1228 SOUTH PATTIE	Break-In Conn	1	0.001	0	0	0.001	
21		128.3	1227 SOUTH LULU	PVC Break-In Conn	1	0.001	0	0	0.001	
			(poor grade / pipe is holding water)							
22		152.3		Sealed Off Wye	2	0.000	0	0	0.000	
23		154.7	(seal broken, lets in dirt)	Sealed Off Wye	4	0.000	0	0	0.000	
24		164.1		Crack-Radial	2	0.002	2	0	0.002	
25		178.6		Sealed Off Wye	1	0.000	0	0	0.000	
26		181.1	(seal broken, lets in dirt)	Sealed Off Wye	3	0.000	0	0	0.000	
27		183.6	(missing pipe / cavity)	Broken Pipe	4	0.030	78	0	0.030	
28		201.2	(cavity)	Broken Pipe	4	0.030	78	0	0.030	
29		202.2	(seal broken, lets in dirt)	Sealed Off Wye	3	0.000	0	0	0.000	
30		203.8		Broken Pipe	2	0.008	44	0	0.008	
31		205.1	1233 SOUTH LULU	Break-In Conn / poor	3	0.004	2	0	0.004	
32		206.2		Broken Pipe	3	0.010	60	0	0.010	
33		207.5	1230 SOUTH PATTIE	Wye Service	1	0.000	0	0	0.000	
34		211.3		5546-541 DS Manhole	1				Poor grade / poor taps / broken sealoffs	