



MH 5744-829
Approx MH depth = 8.4 ft

Install 449 lf of 8" Cured-in-Place Liner

MH 5744-830
Approx MH depth = 9.6 ft

SITE 11



E DUNHAM AVE

S YALE ST

S CLIFTON AVE

S CLIFTON ST

3187

3190

3624

E 31ST ST S

CONNECTICUT



Television Inspection Master Report

1/12/2010

12:45 PM

US Structure: 5744-830
DS Structure: 5744-829

3182 S CLIFTON ST
3187 S CLIFTON ST

Date Insp: 12/2/2009
Dir Televised: Upstream To Downstream

Basin: C01A

Pipe Information

Project No. : I-067 Dia/Ht: 8 Material: VCP Length: 446.0 Slope: 0.400 Tape ID: DVD #0544
Crew: 694

Obs. #	VTR Counter	Distance	Location	Description	Rating	Ratings			Remain (gpm)
						Obsrvd (gpm)	Est. (gpm)	Struct Clean	
1		0.0		5744-830 US Manhole	1				
2		1.5		Broken Pipe	3				
3		12.2		Broken Pipe	3				
4		14.9		Broken Pipe	4				
5		18.7		Broken Pipe	4				
6		25.3		Broken Pipe	3				
7		28.1		Broken Pipe	3				
8		30.9		Roots	3				
9		31.1		Broken Pipe	3				
10		34.0		Roots	3				
11		37.0		Roots	3				
12		40.2		Roots	3				
13		43.3		Roots	3				
14		46.1		Crack-Radial	3				
15		48.7		Roots	3				
16		51.9		Roots	3				
17		55.0		Roots	3				
18		58.3		Roots	3				
19		58.4		Broken Pipe	3				
20		60.8		Roots	4				
21		64.1		Roots	3				
22		64.2		Broken Pipe	4				
23		70.1		Roots	4				
24		73.8		Broken Pipe	3				
25		76.2		Roots	3				
26		85.5		Roots	3				
27		88.5		Roots	3				
28		89.7		Crack-Horizontal	3				
29		91.8		Broken Pipe	2				
30		93.3		Wye Service	4				
Faces 3188 SOUTH CLIFTON / not sealed at the main, but probably abandoned									
31		97.7		Roots	3				
32		98.6		Broken Pipe	3				
33		100.8		Crack-Horizontal	3				
34		104.1		Broken Pipe	3				
35		109.9		Broken Pipe	3				

Television Inspection Master Report

1/12/2010

12:45 PM

US Structure: 5744-830 3182 S CLIFTON ST Date Insp: 12/2/2009 Basin: C01A
 DS Structure: 5744-829 3187 S CLIFTON ST Dir Televised: Upstream To Downstream

36	113.3	Crack-Horizontal	3
37	117.3	Sag	3
38	118.7	Sag	1
39	125.3	Broken Pipe	3
40	129.5	Wye Service	4
Used to serve 3188 SOUTH CLIFTON / Sealed Off, per OCI records			
41	130.7	Broken Pipe	4
42	134.3	Broken Pipe	3
43	137.7	Broken Pipe	3
44	140.5	Broken Pipe	3
45	143.8	Broken Pipe	4
46	149.7	Broken Pipe	3
47	153.5	Broken Pipe	3
48	156.0	Broken Pipe	3
49	178.2	Wye Service	3
3180 SOUTH CLIFTON / possibly active, but broken just outside of the main			
50	192.2	Crack-Horizontal	3
51	208.5	Wye Service	3
3192 SOUTH CLIFTON / broken outside of the main / is this active?			
52	254.4	Wye Service	3
3190 SOUTH CLIFTON / possibly abandoned / broken outside of the main / needs checked			
53	293.7	Wye Service	1
3193 SOUTH CLIFTON / possibly abandoned			
54	339.5	Wye Service	1
3191 SOUTH CLIFTON / possibly active			
55	354.2	Broken Pipe	3
56	356.8	Broken Pipe	3
368.0 North wye / televisor did not stop or note this / could be active / needs checked			
57	399.0	Broken Pipe	3
58	403.2	Crack-Horizontal	3
59	405.8	Crack-Horizontal	3
60	416.1	Wye Service	5
3189 SOUTH CLIFTON / looks completely broken down / is this active?			
61	437.4	Crack-Horizontal	3
62	450.0	Crack-Radial	3
63	451.4	5744-829 DS Manhole	1