

Final Inspection Report of Private Project

Project Number 2004ppw

Inspection Date 11-3-16

Job Name WDS to serve Central Bay Apartment in Silver Springs 2nd

Address or Location 6500 W Central

Consultant Baughman

Inspection Firm Baughman

Contractor Mies

City Inspectors Name Mason

Complete or Defect **defects**

Notes Line 2 & 3 pipe is in the ground but the FDC have not been installed or a pressure test done. Line 1 installed but need to move a FH at Sta 20+08.12 needs moved farther back from curb.

Date Project was Released:

Fire Hydrant Type: