



---

# Sewer CCTV Observations

5/1/2024

9:08 AM

---

<b>Alt Pipe ID:</b>	37753	<b>Inspected Date:</b>	11/5/2020	<b>Survey Direction:</b>	Downstream				
<b>Distance:</b>	<b>CCTV Defect :</b>	<b>Clock 1:</b>	<b>Clock 2:</b>	<b>%</b>	<b>Contin:</b>	<b>Doc:</b>	<b>Struct:</b>	<b>O&amp;M:</b>	<b>Remarks:</b>
0.00	AMH Manhole				False	0	0		6045-004
0.00	MWL Miscellaneous Water Level			5	False	0	0		
285.60	AMH Manhole				False	0	0		6045-003/LINE SEGMENT LOC

---

# Sewer CCTV Observations

5/1/2024

9:10 AM

---

<b>Alt Pipe ID:</b>	37754	<b>Inspected Date:</b>	11/5/2020	<b>Survey Direction:</b>	Downstream				
<b>Distance:</b>	<b>CCTV Defect :</b>	<b>Clock 1:</b>	<b>Clock 2:</b>	<b>%</b>	<b>Contin:</b>	<b>Doc:</b>	<b>Struct:</b>	<b>O&amp;M:</b>	<b>Remarks:</b>
0.00	AMH Manhole				False	0	0		6045-005
0.00	MWL Miscellaneous Water Level			5	False	0	0		
281.30	AMH Manhole				False	0	0		6045-004/LINE SEGMENT LOC

---

# Sewer CCTV Observations

5/1/2024

9:12 AM

---

<b>Alt Pipe ID:</b>	37755	<b>Inspected Date:</b>	11/5/2020	<b>Survey Direction:</b>	Downstream				
<b>Distance:</b>	<b>CCTV Defect :</b>	<b>Clock 1:</b>	<b>Clock 2:</b>	<b>%</b>	<b>Contin:</b>	<b>Doc:</b>	<b>Struct:</b>	<b>O&amp;M:</b>	<b>Remarks:</b>
0.00	AMH Manhole				False	0	0		6045-006
0.00	MWL Miscellaneous Water Level			5	False	0	0		
95.10	AMH Manhole				False	0	0		6045-005/LINE SEGMENT LOC

---

## Sewer CCTV Observations

5/1/2024

9:21 AM

---

<b>Alt Pipe ID:</b>	37756	<b>Inspected Date:</b>	11/5/2020			<b>Survey Direction:</b>	Downstream		
<b>Distance:</b>	<b>CCTV Defect :</b>	<b>Clock 1:</b>	<b>Clock 2:</b>	<b>%</b>	<b>Contin:</b>	<b>Doc:</b>	<b>Struct:</b>	<b>O&amp;M:</b>	<b>Remarks:</b>
0.00	AMH Manhole				False	0	0		6045-007
0.00	MWL Miscellaneous Water Level			5	False	0	0		
220.10	DAZ Deposits Attached Other	10	2	15	False	0	3		
221.50	AMH Manhole				False	0	0		6045-006/LINE SEGMENT LOC

---

## Sewer CCTV Observations

5/1/2024

9:22 AM

---

<b>Alt Pipe ID:</b>	37757	<b>Inspected Date:</b>	12/11/2020	<b>Survey Direction:</b>	Downstream				
<b>Distance:</b>	<b>CCTV Defect :</b>	<b>Clock 1:</b>	<b>Clock 2:</b>	<b>%</b>	<b>Contin:</b>	<b>Doc:</b>	<b>Struct:</b>	<b>O&amp;M:</b>	<b>Remarks:</b>
0.00	AMH Manhole				False	0	0		6045-008
0.00	MWL Miscellaneous Water Level			5	False	0	0		
124.70	AMH Manhole				False	0	0		6045-007/LINE SEGMENT LOC