



Error of Closure Report

North: 1715956.8561' East: 1556503.4587'

Segment #1 : Line

Course: S 89°46'24" W Length: 1145.00'

North: 1715952.3264' East: 1555358.4677'

Segment #2 : Line

Course: N 1°17'49" W Length: 228.62'

North: 1716180.8878' East: 1555353.2931'

Segment #3 : Line

Course: N 88°42'11" E Length: 1144.80'

North: 1716206.7992' East: 1556497.7998'

Segment #4 : Line

Course: S 1°17'49" E Length: 250.00'

North: 1715956.8633' East: 1556503.4583'

Perimeter: 2768.42' Area: 6.289acres

Error Closure: 0.0072 Course: N 3°11'46" W

Error North: 0.00720 East: -0.00040

Precision 1: 384502.78

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgwick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT** (K.S.A. 58-2011a). **NOTICE OF ENDANGERMENT ACTIVITY** (K.S.A. 58-2011b).
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
- NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION** (K.S.A. 58-2011c).
 This may only be filed after filing a prior **NOTICE OF ENDANGERMENT ACTIVITY**. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 07P

Legal Description: Center Section Corner Section: 20 Township: 26 South Range: 3 West

Survey Datum (if known): _____ North: _____ East: _____

Corner Status Prior to Survey: Existent Obliterated Lost Endangered
Monument Condition: Found Set Reset Found Record

Detailed Monument Description: 5/8" Rebar with GSS Cap

REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)

NOTE: ALL MEASUREMENTS ARE HORIZONTAL SLOPED **UNLESS NOTED OTHERWISE.**

3.08' ENE to mag nail SW face corner hedge fence post

14.90' SSE to mag nail North face 24" hedge tree

6.24' ESE to set mag nail West face 30" hedge tree

1.00'± S to fence line East

2.00'± E to fence line North

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Split section between N 1/4 corner - S 1/4 corner & W 1/4 corner & E 1/4 corner.

IDENTIFYING A MARKER

To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 7 V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36

01 03 05 07 09 11 13 15 17 19 21 23 25

A
C
E
G
J
L
N
P
R
T
V
X
Z

The original signature and date shall be across the Land Surveyor's Professional seal.



 Surveyor's signature & date

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgwick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT** (K.S.A. 58-2011a). **NOTICE OF ENDANGERMENT ACTIVITY** (K.S.A. 58-2011b).
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
- NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION** (K.S.A. 58-2011c).
 This may only be filed after filing a prior **NOTICE OF ENDANGERMENT ACTIVITY**. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 05P

Legal Description: West Quarter Section Corner Section: 20 Township: 26 South Range: 3 West

Survey Datum (if known): _____ North: _____ East: _____

Corner Status Prior to Survey: Existent Obliterated Lost Endangered
Monument Condition: Found Set Reset Found Record

Detailed Monument Description: Carriage Bolt

REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)

NOTE: ALL MEASUREMENTS ARE **HORIZONTAL** **SLOPED** **UNLESS NOTED OTHERWISE.**

- 40.00' E to mag nail & washer North face hedge gate post
50.33' NE to top center UGT pedestal
53.87' SW to mag nail & washer SE face power pole brace post
40.50' WNW to set mag nail top corner hedge fence post

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Ties of record & magnetic locator.

IDENTIFYING A MARKER

To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 7 V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1	A						
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12	C						
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13	G						
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24	J						
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25	N						
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36	P						
						R						
						T						
						V						
						X						
						Z						
01	03	05	07	09	11	13	15	17	19	21	23	25

The original signature and date shall be across the Land Surveyor's Professional seal.



 Surveyor's signature & date

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgwick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT** (K.S.A. 58-2011a). **NOTICE OF ENDANGERMENT ACTIVITY** (K.S.A. 58-2011b).
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
 NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION (K.S.A. 58-2011c).
 This may only be filed after filing a prior NOTICE OF ENDANGERMENT ACTIVITY. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 07R
 Legal Description: South Quarter Section Corner Section: 20 Township: 26 South Range: 3 West
 Survey Datum (if known): _____ North: _____ East: _____
 Corner Status Prior to Survey: Existent Obliterated Lost Endangered
 Monument Condition: Found Set Reset Found Record
 Detailed Monument Description: 5/8" Rebar
REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)
NOTE: ALL MEASUREMENTS ARE HORIZONTAL SLOPED **UNLESS NOTED OTHERWISE.**
30.75' S to spike top corner hedge fence post
29.87' N to double nails East face lone hedge post
38.00' SSW to bent spike top corner hedge fence post
0.00' N to centerline road E-W (45th Street North)

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Ties of record & magnetic locator.

IDENTIFYING A MARKER

To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 7 V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1	A
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12	C
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13	E
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24	G
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25	J
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36	L
						N
						P
						R
						T
						V
						X
						Z

01 03 05 07 09 11 13 15 17 19 21 23 25

The original signature and date shall be across the Land Surveyor's Professional seal.



 Surveyor's signature & date

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgewick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT** (K.S.A. 58-2011a). **NOTICE OF ENDANGERMENT ACTIVITY** (K.S.A. 58-2011b).
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
 NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION (K.S.A. 58-2011c).
 This may only be filed after filing a prior NOTICE OF ENDANGERMENT ACTIVITY. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 07N
 Legal Description: North Quarter Section Corner Section: 20 Township: 26 South Range: 3 West
 Survey Datum (if known): _____ North: _____ East: _____
 Corner Status Prior to Survey: Existent Obliterated Lost Endangered
 Monument Condition: Found Set Reset Found Record
 Detailed Monument Description: 3/4" Pipe
REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)
NOTE: ALL MEASUREMENTS ARE HORIZONTAL SLOPED **UNLESS NOTED OTHERWISE.**
54.80' SW to set mag nail North face power pole
22.31' NNE to set "X" cut top West end 15" RCP
0.00' N to centerline road E-W (53rd Street North)
58.10' S to top center 6" steel post @ SW corner gate

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Ties of record & magnetic locator.

IDENTIFYING A MARKER


To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 | 7 | V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1	A
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12	C
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13	E
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24	G
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25	J
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36	L
						N
						P
						R
						T
						V
						X
						Z
01	03	05	07	09	11	13
15	17	19	21	23	25	

The original signature and date shall be across the Land Surveyor's Professional seal.



 Surveyor's signature & date

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgwick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT** (K.S.A. 58-2011a). **NOTICE OF ENDANGERMENT ACTIVITY** (K.S.A. 58-2011b).
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
 NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION (K.S.A. 58-2011c).
 This may only be filed after filing a prior NOTICE OF ENDANGERMENT ACTIVITY. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 09P

Legal Description: East Quarter Section Corner Section: 20 Township: 26 South Range: 3 West

Survey Datum (if known): _____ North: _____ East: _____

Corner Status Prior to Survey: Existent Obliterated Lost Endangered
 Monument Condition: Found Set Reset Found Record

Detailed Monument Description: 1" Dia. Pipe

REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)

NOTE: ALL MEASUREMENTS ARE HORIZONTAL SLOPED **UNLESS NOTED OTHERWISE.**

36.60' WNW to set mag nail East face 16" walnut tree

35.55' WSW to set mag nail East face 10" hackberry tree

72.10' SE to set mag nail West face power pole

0.00' E to centerline road N-S (279th Street West)

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Ties of record & magnetic locator.

IDENTIFYING A MARKER

To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 7 V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36

01 03 05 07 09 11 13 15 17 19 21 23 25

A
C
E
G
J
L
N
P
R
T
V
X
Z

The original signature and date shall be across the Land Surveyor's Professional seal.



 Surveyor's signature & date

LAND SURVEY REFERENCE REPORT
 Department of Archives
 Kansas State Historical Society
 6425 SW Sixth Avenue, Topeka, KS 66615-1099
 (785) 272-8681 Ext. 322 FAX (785) 272-8682

FOR OFFICIAL USE ONLY

Land Surveyor: Daniel E. Garber
Company: Garber Surveying Service, P.A.
Street Address: 2908 North Plum Street
City, State: Hutchinson, KS
Zip Code: 67502

L.S. Reg. Number: 683
Project Number: G2016-367
Telephone Number: 620-665-7032
Date of Survey: July 8, 2016
County of Survey: Sedgwick

This report is filed as a (check only one):

- SURVEY REFERENCE REPORT (K.S.A. 58-2011a).** **NOTICE OF ENDANGERMENT ACTIVITY (K.S.A. 58-2011b).**
 There is a \$4.00 per corner filing fee, which must accompany the Land Survey Reference Report.
- NOTICE OF COMPLETION OF ENDANGERMENT ACTIVITY AND REPORT OF RESTORATION (K.S.A. 58-2011c).**
 This may only be filed after filing a prior NOTICE OF ENDANGERMENT ACTIVITY. There is no filing fee.
 Endangerment report was filed on _____.

LOCATION CODE OF MARKER IN TOWNSHIP (see illustration below): 09N

Legal Description: Northeast Section Corner Section: 20 Township: 26 South Range: 3 West

Survey Datum (if known): _____ North: _____ East: _____

Corner Status Prior to Survey: Existing Obliterated Lost Endangered
 Monument Condition: Found Set Reset Found Record

Detailed Monument Description: 5/8" Rebar

REFERENCE MARKS AND MEASUREMENTS: (Please, no symbols or abbreviations.)

NOTE: ALL MEASUREMENTS ARE HORIZONTAL SLOPED UNLESS NOTED OTHERWISE.

- 43.25' SE to mag nail West face power pole
- 79.60' WSW to mag nail East face power pole
- 40.75' NW to top center UGT pedestal
- 0.00' S to centerline road E-W (53rd Street North)

DETAILED METHOD OF RECOVERY OR ESTABLISHMENT: Ties of record & magnetic locator.

IDENTIFYING A MARKER

To identify the location of a marker in a township, use the following standard alpha-numeric grid to designate an identifier for a given section corner or intersection.

For Example: The southwest corner of Section 26 would be designated by the identifier "17V". This is the "LOCATION CODE OF MARKER IN TOWNSHIP".

1 7 V

Sec 6	Sec 5	Sec 4	Sec 3	Sec 2	Sec 1
Sec 7	Sec 8	Sec 9	Sec 10	Sec 11	Sec 12
Sec 18	Sec 17	Sec 16	Sec 15	Sec 14	Sec 13
Sec 19	Sec 20	Sec 21	Sec 22	Sec 23	Sec 24
Sec 30	Sec 29	Sec 28	Sec 27	Sec 26	Sec 25
Sec 31	Sec 32	Sec 33	Sec 34	Sec 35	Sec 36

01 03 05 07 09 11 13 15 17 19 21 23 25

A
C
E
G
J
L
N
P
R
T
V
X
Z

The original signature and date shall be across the Land Surveyor's Professional seal.



Surveyor's signature & date