

## **STREET FLOW CHECKS**

<b>Basin</b>	<b>Node</b>	<b>Q2</b>	<b>Q100</b>
1H	102	2.86	7.49
1I	101	1.12	2.93
1J	103	0.95	2.50
1K	104	3.00	7.86
1M	112	4.12	10.80
1N	114	2.74	7.18
1O	111	2.67	6.99
1P	113	4.93	12.92
1Q	131	1.57	4.12
1R	133	1.57	4.12
1S	132	5.93	15.54
1T	134	10.16	26.64

### **2 Year**

<b>Node</b>	<b>Q2</b>	<b>Street Slope</b>	<b>d</b>	<b>dmax</b>	<b>Comment</b>
134	10.16	0.50	0.46	0.55	OK

\* By inspection, all nodes are OK

### **100 Year**

<b>Location</b>	<b>Q100</b>	<b>Qpipe</b>	<b>Qstreet</b>	<b>S</b>	<b>Qmax</b>	<b>Comment</b>
Approaching node 134	26.64	0.00	26.64	0.50	37.66	OK

\* By inspection, all nodes are OK