DAILY CONSTRUCTION INSPECTION REPORT

Date: 9-25-24

City Project Number:

KEM Proj. Number:

Contractor: Apex

Inspector: Mark Gelvin

Weather: 81° Sunny

Construction Activities:

excavate for City taps

Station 0+00.20 Line 1

Station 0+00.00 Line 2

DAILY CONSTRUCTION INSPECTION REPORT

Date: 9-26-24

City Project Number: 2022-032890 PPW(54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 80° Sunny

Construction Activities: Station 0+00.00 Line 1
set fire hydrant, dry blocks, pour thrust blocks, pea gravel, tracer wire,

8" water line 2 Station 0+00.06

thrust blocks @ tap, 45° bend

Station 0+07.00

thrust blocks @ 90° bend

DAILY CONSTRUCTION INSPECTION REPORT

Date: 9-27-24

City Project Number: 2022-032890 PPW(54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 82° sunny

Construction Activities:

8" water line 2 station 0+07.00 — station 1+50
excavate, sand bed, install pipe, tracer wire,
sand cover, dig tape, back fill

DAILY CONSTRUCTION INSPECTION REPORT

Date: 9-28-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 87° Sunny

Construction Activities:

8" water line 2 station 1+50 – 2+36.35

~~Back fill~~

~~Flush - Vibrate~~

excavate, sand bed, install pipe, tracer wire, sand cover, dig tape, back fill

DAILY CONSTRUCTION INSPECTION REPORT

Date: 9-30-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehner

Weather: 87° Sunny

Construction Activities:

8" water line 2

Back fill

DAILY CONSTRUCTION INSPECTION REPORT

Date: 10-1-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 75° Sunny

Construction Activities:

Finish backfill water line 2 - flush & vibrate Sta. 0+00 to Sta. 2+36.35

Pressure test water lines 1 & 2

Line 1 pass

Line 2 pass

DAILY CONSTRUCTION INSPECTION REPORT

Date: 10-2-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 80° Sunny

Construction Activities: Water Line 2 Sta. 0+00 – Sta. 2+36.35
Water quality testing

DAILY CONSTRUCTION INSPECTION REPORT

Date: 10-7-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gelinas

Weather:

Construction Activities:

Re-do Water Quality testing – water line 2 sta. 0+00 – sta. 2+36.35

Apex used incorrect forms on 10-2-24

DAILY CONSTRUCTION INSPECTION REPORT

Date: 10-14-24

City Project Number: 2022-032890 PPW (54030980)

KEM Proj. Number: 24-139

Contractor: Apex

Inspector: Mark Gehrer

Weather: 67° Sunny

Construction Activities:

Water line 2 shut down and tie in. Backfill, compact Sta. 2+43.35

Plug abandoned 8" waterline apx. sta. 0+09 and Sta. 2+42

City of Wichita opened valves

All valves are open