



CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
				2+63.4	2+53.5	2+51		2001-00591 #221	501	510		3-19-01 4-23-09
2	111.99	106.11	5.88		2+28.5	2+26	#1516	2001-00592 #633	501	510		11-9-22 8-4-19 3-19-01 7-14-11
1	108.59	105.95	2.64		2+04.5	2+02						
					1+78.5	1+76						
					1+55.5	1+53						
					1+23.5	1+21	#1367	#361	415	510		11-12-19 6-15-09
					0+95.5	0+93	#1053	#1053-03012	510	510		12-2-05 12-19-25
					0+69.5	0+67						
					0+42.5	0+40						
0	108.89	105.79	3.10	0+0	0+13.5	0+11	#386					4-25-22
				1+85.4 (OH)		1+68						
						1+48	#674		1944			12-9-10
1	108.43	105.95	2.48			1+25	16845		1936			8-28-86
						0+97						
				0+93.8 (OH)		0+72						
						0+46	75-200447 #163		1992			12-12-05 3-6-26
0						0+17			University			
4	108.61	104.70	3.91	4+32		4+16			1912			10-26-25
						3+91	#1175		University			
						3+67						
					3+32	3+44	#643	519 S. Glenn	1908			10-13-09
3	108.81	104.60	4.21			3+21	#1428		University			9-26-28
						2+88						
						2+70	#1519	519 S. Glenn	1920			2-15-62
2	108.51	104.50	4.01			2+44	#57	751 1/2 N. 2487	537 R			2-5-10 2-19-01 2-15-62
						1+35	#364		1824			5-4-26
1	108.81	104.40	4.41			1+09			University			
						0+84						
						0+59						
						0+42	#78		1824			3-4-09
0				0+0	m.H. 13+25.9 on Main H.	0+12	#120		1816			3-24-09
				13+25.9								
13	108.91	104.30	4.61			13+03.5						
						12+72						
						12+49	#255	2001-01609	1804 R			6-1-12
						12+26	#177		1809			3-11-20
12	108.31	104.20	4.11			12+02.5	#323		UNIVERSITY			4-23-20
11	109.11	104.10	5.01			11+77			542			
						10+63						
						10+36.5	#723					11-17-09
10	110.71	104.11	6.71			10+11	#354		1710			1-23-09
						9+62						
				9+50.5		9+20	#242		1710			5-3-09
9	109.72	103.90	5.8			8+86	#628		1710			10-5-09
						8+58						
						8+23	#21	93-01540	1700 R			8-12-93 2-4-09
8	109.12	103.80	5.32			6+55.5						
7	109.12	103.70	5.42			6+69						
						6+53						
						6+17.5	#119		1616			3-24-09
6	109.82	103.60	6.22			5+35	Fl. Drain					5-20-13
5	110.22	103.50	6.72	5+75		5+54						
						4+92.5	#348		527 S.			1-23-09
4	108.79	103.40	5.39		4+85.5	4+83	#150	521 S. Fern				4-1-09
						3+30.5						
						3+02	#568		1422			9-9-09
						2+78.5	#258		528 S.			7-16-28
					2+52.5	2+55	#142	2001-00519 530 S. Fern	1422 S. Seebelow			1-24-09 6-25-28
						2+29						
2	108.99	103.20	5.79			2+03	#230		1416			5-18-12
				1+88		1+77.5						
						1+54	#146		1408			3-31-09
						1+28	#470		1418			8-8-10
1	108.29	103.10	5.19			1+00						
					0+43.7	0+76.5	#340	500-35930				11-10-72 1-21-09
0	108.79	103.00	5.79	0+0								

see next page

16845  
 Deal C 45171 - 1816 University (Brewer) 8-14-86 (4+15.4 OH)  
 C 36067 - 1404 University - 6-5-14 - Fern (OH) 12+43.5 - w/ 13+11.5 (6.1W)  
 C 18489 - 1809 University - 11-22-72 - Jay Seater (0+85.5)  
 #1752 - Top - 1921 Fern - 11-28-23  
 #248 - 1420 University - 3-25-30 - C.M. Wyant  
 #1375 - 1809 University - private in garden - 1-9-61  
 #1519 - Top 1900 University - Birch willow & Dec. 2-15-62 (3+11)  
 #2000-00519 - 1422 W University - Bowers Pkg. - 4" SCH 40 1/8" fall - Replaced east house sewer - 30ft section - Tied back to exist sewer  
 93-26213-7 10-5-93 530 S. Glenn (144) UNIVERSITY  
 UNIV. FRIENDS (CHURCH) - 150 FT West of MH 1+50,  
 4" SCH 40 PVC; 2" PVC; 3-45 H; 1-45 V; 1-4" trap