

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
24	118.80	114.55	4.25	F.T. 24+29.5	24+25	24+22.5	#556		1347 Jackson			6-15-11
					24+08.5	24+06						
					23+83.5	23+81	#1758		511 W. Jackson			3-15-48
					23+62	23+59.5	#570		1341 Jackson			8-13-09
					23+34.5	23+32						
23	119.00	114.45	4.55		23+08.5	23+06	#205	#71	1337 Jackson			2-15-24
					22+81.5	22+79	#683		1336 Lewellen			6-25-25
					22+56.5	22+54	#578					8-23-18
					22+31.5	22+29	#793	#520				7-6-22
22	118.00	114.35	3.65		22+06	22+03.5						8-28-18
					21+80.5	21+78	#379					6-9-17
					21+55.5	21+53	#357					3-12-23
					21+30.5	21+28	#557					9-9-18
21	117.40	114.25	3.15	21+11	21+08.5							
					21+01							
						20+81						
					20+78	20+75.5	#435	#595				8-27-15
					20+53.5	20+51	#1427					11-8-10
					20+28.5	20+26	#79	#160	1314 Lewellen	1315 Jackson		9-26-23
20	117.07	114.15	2.92		20+06	20+01						8-21-34
					19+78.5	19+76						2-11-24
					19+53.5	19+51	#717		1311 Jackson			4/25/73
					19+28.5	19+26	#604	#1681	1310 Lewellen	1307 Jackson		11-12-09
19	117.37	114.05	3.32		19+03	19+00.5	#264	#597	1303 Lewellen	1305 Jackson		11-19-03
18	118.30	113.95	4.35		18+72.5	18+57	#244	#540	1302 Lewellen	1305 Jackson		3-28-24
17	119.30	113.85	5.45	17+89					1305 Jackson			11-14-23
												4-7-20
												9-20-09
												8-27-09
21	118.27	114.95	3.32	F.T. 21+23.5	21+12		#723		1304 Lewellen			4-27-17
					20+88.5							8-27-09
					20+63							
					20+37.5		#827		1359 Lewellen			1-29-19
20	118.67	114.85	3.82		20+12							4-9-19
					19+90.3							
					19+85		#1280		1343-45 Lewellen			12-24-21
					19+59.5		#1568					11-18-22
					19+34							
19	118.87	114.75	4.12		19+09		#575		1341 Lewellen			5-26-25
					18+84							
					18+58		#420		1335 R Lewellen			5-18-21
					18+32		#132					1-31-21
18	118.67	114.65	4.02		18+07		#945		1334 R Lewellen			3-14-10
					17+84		#358		1325 Lewellen			4-28-03
					17+58.5							9-4-28
					17+33.5							6-15-09
17	118.57	114.55	4.02		17+08		#816					10-6-11
					16+84.8							
					16+81.5							
					16+58		#155					3-21-10
					16+32.5							
16	117.27	114.45	2.85		16+07		#436		1323 Lewellen			10-9-29
					15+81		#98		1311 Lewellen			3-3-11
					15+56.5							
					15+31		#742					8-31-21
15		114.35			15+05.5		#56		1309 Lewellen			1-30-22
14+85	117.27	114.34	2.93		14+80		#878		1307 Lewellen			5-14-01
					14+54.5							4-18-24
14					14+32		#1683		1301 Lewellen			7-22-24
					13+84.5							
13+47	119.27	114.20	5.07		12+89.5	12+92						
12+47	120.17	114.10	6.07	12+14.5								
2002-00547-1303 N Jackson 2/28/02 Clearwater - 6" clay tile line slo that served 1303 N Jackson 12' E of NE corner of house at 512 W 12th. NOTE: This sewer still serves 512 W 12th N.												
R- 2001-00225- 13101-1335 N Lewellen Ave - Ark Valley P/bq - 4" sch 40 TRAP INSTALLED, Replace middle of Line - 2-4" Fernco Clamps												
R #689 519 W 13th 7-3-80 J.C. Sewers												
7/6 13322 527 W 13th 3-26-85 Enrich (65' S of Mt) 27' W												
7/6 13947 527 W 13th 6-4-85 " (23+64.5) 65' S of Mt												

#617- Tap - 620 W. 12th - 7-21-26
 #2430- Private line connection - 633 W. 13th - Callison P/bq. 11-15-45
 #551- Tap East - 80' So. of 19490.3
 #4709 - Used old connection - 603 W. 13th - 5-22-51 - Frederick P/bq.
 #13430 Tap - 523 W. 13th Phil's Trenching 10-3-60 (23+63.5)
 #2131 2/19/92 1331 N Lewellen (Det'd Sak.) - Betzen (17+83.8 tap)
 #94-12796-7 8/10/94 1347 N Lewellen - separate bldg from 1349 Lewellen (near house) Tap 17+87.3 = 4" sch 40 P.V.C.
 94-10163-7 6-23-94 1349 N Lewellen - repaired 50' off main = 4" sch 40 P.V.C.