



CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
25	117.92	112.77	5.15		25+81.5	25+79		#367				5-5-21
					25+56.5	25+54		#47				2-12-15
					25+30.5	25+28	2000-02642	#691	1148 R	12/100		
					25+04.5	25+02		#692	Coolidge	9-17-17		
					24+80	24+77.5	Pre-4" PVC 10'	#227	1146	9-17-17		
24	117.39	112.47	4.92	24+20.9	24+51.5	24+49		#246	1140	4-4-21	6-7-17	
					24+29.5	24+27		#373	Coolidge ?			
					24+04.5	24+02		#270	1134	5-11-18		
					23+79.5	23+77			Coolidge			
					23+53.5	23+51		#1219			9-11-19	
23	117.63	112.37	5.26		23+28	23+25.5		#47	1132	3-1-16	4-19-15	
					23+02.5	23+00		#79	Coolidge			
					22+77.5	22+75			1130	3-18-16		
					22+52	22+49.5			Coolidge			
					22+26.5	22+24		#413	1126	12-27-15	4-21-17	
22	117.24	112.27	4.97		22+00.5			#939	1119	5-22-19		
									Coolidge			
21	117.33	112.17	5.16	21+12	21+98	21+98		#673			12-8-10	
					21+76.5	21+74						
					21+49.5	21+47						
					21+23.5	21+21		#1321	1110	10-25-19	8-29-18	
					20+98.5	20+96		#289	Coolidge			
20	117.08	112.07	5.01		20+74	20+71.5		#842	1104	5-20-18	11-4-14	
					20+48.5	20+46			Coolidge			
					20+22.5	20+20		#680			12-26-16	
					19+28.5	19+26						
					19+02.5	19+00		#809	1102	10-29-20	11-26-19	
18	117.48	111.87	5.61	18+12.2	18+77.5	18+75		#208	1052	4-30-15	8-16-21	
					18+50.5	18+48		#16	Coolidge			
					18+22.5	18+20			1047	1-7-22		
					17+98.5	17+96		#469	Coolidge			
					17+70.5	17+68		#928	1041	5-9-22	4-11-19	
17	117.73	111.77	5.96		17+46.5	17+44						
					17+20.5	17+18						
					16+96.3	16+93.8		#1198	1036	9-15-22	9-16-24	
					16+70.5	16+68		#1280	Coolidge			
					16+44.5	16+42		#670	1032	10-3-22	10-19-59	
16	117.37	111.67	5.70		16+19.5	16+17		#225	1026	5-4-23		
					15+94	15+91.5		#449	Coolidge			
					15+74			#442			5-27-20	
					15+68.5	15+66		#172	1022	3-13-22		
					15+41	15+38.5		#571	Coolidge		6-28-21	
15	117.26	111.57	5.69	15+12.1	15+15.5	15+13						
					14+90	14+87.5		#570			6-28-21	
					14+64	14+61.5		#44	1014	6-2-34	2-21-17	
					14+36.5	14+34		#83	Coolidge			
					14+12	14+09.5		#187				
14	117.28	111.47	5.81		13+86.5	13+84		#1531	1002	6-2-36		
					13+61	13+58.5		#3	Coolidge			
											11-13-22	1-5-17
13	117.21	111.37	5.84	13+10.0 (O.H.)	4" sch PVC.							
					13+83.6			#4-20363-7	1001 N. R.		12-20-94	

SWR2006-01597-1319 N Woodrow - repair - Even temp - 4/22/06

SWR2006-02781-1717 W Briggs - full replac - 200' s gml, (1) 45', (1) 22", (1) twin (1) fanco shallow 4" sch 40 PVC  
(1) twin (1) - Olson Swel - 11/10/06

96-2962-7 3-5-96 1149 N Woodrow - Brand P/ly - 56' N. of MH (24+76.9)

#699-Top - 9-15-20  
#181-Top - 3-15-22 1016 Coolidge