

DISTA - S.S.#12  
1912

CENTRAL AVE.		AVE.	
25	2	137	23+89.91
	4		3
	6		5
	8		7
	10		9
	12		11
	14		13
436	16	22+13 (C.O.N.)	15
	18		17
	20		19
	22		21
	24		23
	26		25
	28	20+62.27	27
	30		29
	32		31
414	34		33
	36		35
	38	19+38.5 (C.O.N.)	37
410	40		39
	42		41
	44		43
404	46		45
	48		47

425 N Belmont assigned additional address for Det of Garage + Apt of 427 N Belmont 2118198

3<sup>RD</sup> ST. REHAB MH 17+63.2

28.7	50		49	29.6
25	52		51	25
	54		53	
	56		55	
	58	16+19.57 (C.O.N.)	57	
	60		59	
	62		61	
340	64		63	339
	66		65	
	68		67	
	70		69	
	72	REHAB MH 14+55.71		
	74		73	
	76		75	
	78		77	
	80		79	
	82		81	
	84	12+95.83 (C.O.N.)	83	
	86		85	
	88		87	
	90		89	
	92		91	
	94		93	
25	96	REHAB MH 11+39.1	95	25

1992 SANITARY SEWER REHABILITATION PROGRAM - PHASE I  
 PROJ. # 468-82220 (631879)  
 BUILT BY INSITUFORM PLAINS, INC.  
 BOOKED 3-17-93 FROM AS BUILTS

RECONNECTIONS

STATION	ADDRESS	DIRECTION
16+70.6	345 Belmont	East
16+68.5	345 Belmont	East
16+26.7	345 Belmont	East
15+70.4	340 Broadview	West
15+67.8	339 Belmont	East
15+03.1	324 Broadview	West
14+96.9	339 Belmont	East
14+71.8	323 Belmont	East
14+17.6	316 Broadview	West
13+37.2	319 Belmont	East
13+36.6	312 Broadview	West
12+68	308 Broadview	West
12+43.2	No Address	West
12+15.7	301 Belmont + Garage Apt.	East
11+97.9	302 Broadview	West

CONSTRUCTION RECORD							SERVICE RECORD					
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
11	195.16	181.06	14.10	11 + 39.1	11 + 63 + 88	11 + 60.5 + 85.5	#1100	Repair (7410)	501 N. Belmont		7-26-19	3-20-68
12	195.36	181.36	14.00		12 + 13 + 38 + 63 + 89	12 + 10.5 + 35.5 + 60.5 + 86.5	#1101				7-26-19	
13	194.86	181.66	13.20		13 + 13.5 + 36.5 + 61.5 + 87	13 + 11 + 34 + 59 + 84.5	#15962		319 N. Belmont			1-31-62
14	194.56	181.96	12.60		14 + 12 + 37.5 14 + 55 + 67 + 92	14 + 09.5 + 35 + 64.5 + 89.5	#96 #604			315 N. Belmont	2-12-20	6-3-22
15	194.56	182.26	12.30		15 + 14.5 + 39.5 + 64.5 + 89.5	15 + 12 + 37 + 62 + 87	#1028	2005-0937 #446	346 N. Broadview	339 N. Belmont	9-17-25	4-20-00 9-2-15
16	193.63	182.56	11.07		16 + 14.5 + 40 + 65.5 + 90.5	16 + 12 + 37.5 + 63 + 88	#342 #610				3-8-23 10-13-14	5-8-14
17	192.83	182.86	9.97		17 + 15.5 17 + 63.2	17 + 13						
18	191.53	183.16	8.37		18 + 06.5 + 32 + 57.5 + 82.5	18 + 04 + 29.5 + 55 + 80	#5443		404 N. Broadview		4-14-66	
19	191.93	183.46	8.47		19 + 09.5 + 34.5 + 59.5 + 85	19 + 07 + 32 + 57 + 82.5	#279 #357			410 N. Broadview	1-23-80	
20	192.13	183.76	8.37		20 + 10.5 + 35.5 + 61 + 86	20 + 08 + 33 + 58.5 + 83.5	#2612	#1924 #425	424 N. Broadview	411 N. Belmont	8-27-40	8-22-24 5-18-21
21	190.13	184.06	6.07	20 + 62.2	21 + 11.5 + 35.5 + 61 21 + 87	21 + 09 + 33 + 58.5 + 84.5	#668 #257				5-4-23	2-23-23
22	189.73	184.36	5.37		22 + 11.5 + 38.5 + 62.5 22 + 87.5	22 + 09 + 36 + 60 + 85	#68 #285		447 N. Belmont		2-3-27	8-7-18
23	188.83	184.66	4.17		23 + 13 + 38.5 + 66	23 + 10.5 + 36 + 63.5	#1228		448 N. Broadview		8-7-22 8-18-23	
	190.23	184.92	5.31	23 + 89.9								

2001-00653- 3/23/01- 436 N Broadview- Padgett Exc- Repair 4" SCH40 Predco 117' N of (HH 20 + 62.2 (21 + 79.2))  
1422, 1445

#322- Top - 3/2 N. Broadview - 4-2-28  
#2299- Top - 302 N. Broadview - 9-24-45 - C.R. Alexander