



DIST. F-5.5. NO. 20-1920

1203 S Lulu - house to be
 worked. DO NOT issue a
 permit for new house
 unless PRU ESMIT
 granted from owner
 of 1317-12 Lincoln &
 Nam RT made
 3-8-07
 BR

2003-03042-11/19/03-1225 S Lulu - Bobs Sewer
 4" PVC - TWIN CO

SWR 2003-00653 3/17/03 1237 S Lulu Boardman (Rep at house approx 20' out)
 4" PVC 40 4" TWO WAY CO at house - Soil pipe extension 20' out from house

D-108

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	102.77	95.44	7.33	0+0	+35.5	+33	#1883		1445	Ellis		12-20-23
					+61	+58.5	#1015		1454	Ellis	11-24-26	
					+86	+83.5						
1	102.00	95.64	6.36		+12.5	+10.0	#147		1443	Ellis		4-9-24
					+39.0	+36.5			1446	1447		
					+63.5	+61	#393	#373	Lulu	Ellis	5-17-26	3-4-24
					+90	+87.5	#264		1442	Lulu	6-20-47	
2	102.27	95.84	6.43	+19.3	+16	+13.5	#1984		1436	1439		9-2-24
					+42	+39.5	#2019		Lulu	1437		6-5-42
					+67.5	+65.0	#391			Ellis		5-11-26
					+93.5	+91.0	#3		1432	Lulu	8-28-41	
3	103.16	96.04	7.12		+21	+18.5	#60			1435		1-29-26
					+44.5	+42	#102			1431		2-17-27
					+71	+68.5	#640			Ellis		
					+96	+93.5						
4	102.66	96.24	6.42	+39.8	+22.5	+20	#1173		1417	Ellis		8-6-23
					+48	+45.5	#1635		1418	Lulu	2-21-75	3-18-47
					+75	+72.5	#450		1415	Ellis		6-20-23
					5+00	+97.5	#367		1412	Lulu	6-1-26	5-11-20
5	102.78	96.44	6.34		+25.5	+23	#1981		1406-8	Lulu		7-23-52
					+50.5	+48	#49954	#373	1405-05	1403		6-17-75
					+76.5	+74			Ellis			5-13-20
					+98.5							
6	102.67	96.64	6.03	+62.8	+01		#529		1400	Lulu	3-13-75	3-21-24
					+26.5	+24						
7	102.99	96.92	6.07									
8	103.11	97.06	6.05	+50								
20+00	105.52	99.44	6.08	+15.4								
21+00	105.47	99.64	5.83		21 +08.2	+05.7	#189		1258	Pattie		2-6-23
					21 +33.7	+31.2	#630		1249	Lulu		4-1-24
					21 +59.7	+57.2	#290		1237	Lulu		4-19-20
					21 +85.2	+72.7	#2647		1247	Lulu		10-11-50
22+00	107.20	99.84	7.36		22 +15.2	+10.7	#567		1238	Pattie		7-15-20
					22 +37.7	+48.7	#639					8-17-20
					22 +62.7	+60.2	#1901		1235	Lulu		12-26-23
					22 +91.2	+85.7	#826	#1646	1236	Pattie	1233	11-4-20
23+00	107.40	100.04	7.36	+84.5	23 +14.2	+11.7	#1106		1230	Pattie		9-14-22
					23 +41.2	+38.7	#510		1225	Lulu		6-20-27
					23 +66.7	+64.2	#1587		1228	Pattie		11-4-29
					23 +93.2	+90.7	#1199		1229	Pattie		6-31-56
24+00	106.20	100.24	5.96	+93.7	24 +19.7	+17.2	#172		1226	Pattie		1-31-23
					24 +44.2	+41.7	#501		1221	Lulu		3-2-74
					24 +70.2	+67.7	#135		1224	Pattie		3-2-94
					24 +96.2	+93.7	#838		1219	Pattie		1-29-23
25+00	106.56	100.44	6.12		25 +13.7	No Y	#420	#1270	1220 R	1219		3-9-86
					25 +48.2	+45.7	#715	#518	1210	Pattie	1211	
					25 +73.2	+70.7	#331					9-20-20
					25 +89.7	+96.7						4-25-21
26+00	106.97	100.64	6.33		26 +23.7	+21.2	#1634	#1594	1224	Pattie		7-15-24
					+50.2	+47.7	#324	#1731	1200	Pattie		4-15-22
					26 +78.7	+76.2	#272		1317	E. Lincoln		11-23-23
27+00	107.55	100.87	6.68	+01.5					1317	E. Lincoln		6-4-37

#1825-120-1420 Lulu - 9-9-39 - R.E. Bayer
 #4941-1442-Lulu-5-25-55-Hinshaw Plog.
 #1952-1311 E. Lincoln - 8-5-57 - Donaghy
 *1203 S. Lulu - Pallett Excavation - 10/2/95 - D.L. replaced 3 ft sewer of 4" PVC 40 tied
 Both ends onto clay tile -- note: this sewer connects to main 40 ft South of MH

Tap - 048442-1418 Lulu - 2/24/75 - Rutledge (4+65.4)
 #1435 11/5/91 1214 S. Pattie - Jack Blum - (4" PVC 40 FROM GARAGE TO TOP of MAIN
 5' S. of MH)