



LAT. 2 - DIST. 2 - S. S. NO. 20
W. B. CARTER - 1938

1-150

D-204

CONSTRUCTION RECORD							SERVICE RECORD					
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	123.00	113.28	9.72	0+0	0+64.5	0+61.6		# 564		1923 Hood		5-28-46
1+0	122.70	113.38	9.32		0+91.5	0+88.5						
					1+15.0	1+12.0						
					1+39.0	1+36.0						
					1+66.4	1+63.4		# 798		1913 Hood		9-25-47
				1+73.3	1+91.5	1+88.0		# 648		1907 Hood		11-20-41
2+0	122.80	113.48	9.32		2+12.5	2+11.5		# 2001-00450		1917 R Hood	See Below	3-1-00
					2+31.5	2+28.5		# 765				10-9-46
					2+65.6	2+62.6		# 1784	# 766	1920-22 Garland Hood		3-17-48
					2+90.4	2+87.4		# 565	# 961	1926-28 Hood		8-28-46
3+0	122.30	113.58	9.72		3+17.7	3+14.7		# 1785	# 961	1926-28 Hood		3-17-48
					3+41.5	3+38.5						
					3+66.0	3+63.0		# 962		1933 Hood		11-20-46
					3+93.4	3+90.4		# 1786	# 963	1932-34 Hood		3-17-48
4+0	122.60	113.68	8.92		4+17.0	4+14.0		# 1017	# 964	1940 Hood		11-20-46
					4+41.0	4+38.0				1943 Hood		11-20-46
				4+49.5	4+68.5	4+65.5		# 965	# 965	1949 Hood	See Below	8-30-99
5+0	122.60	113.78	8.82		5+13.0	5+10.0		# 1016	# 965	1949 Hood		10-27-47
					5+44.0	5+41.0						
					5+68.2	5+65.2		# 909	# 910	1955 Hood		7-18-49
6+0	122.60	113.88	8.72		6+17.8	6+14.8		# 664	# 910	1956 Hood		8-18-47
					6+41.4	6+38.4				1957 Hood		7-18-47
					6+61.0	6+58.0						
7+0	122.80	113.98	8.22	6+76.0	7+23.7	7+20.7		# 1393		2002 Hood		6-26-50
					7+47.4	7+44.4				1302 Hood		4-17-59
					7+75.3	7+72.3		# 10066	# 1662	2009 Hood		5-4-92
					7+99.5	7+96.5						
8+0	122.40	114.08	8.92		8+23.5	8+20.5		# 1041		2010 Hood		6-12-48
					8+50.6	8+47.6		# 1470		2016 Hood		11-10-48
					8+75.2	8+72.2						
					8+97.0							
9+0	122.40	114.18	8.22	9+07.5	9+05.4	9+22.7		# 5203		2022 Hood		7-10-51
					9+25.7	9+22.7		# 3567		2021 Hood		6-2-41
					9+50.2	9+47.2						
					9+74.4	9+71.4		# 2967	# 1533	2023 Hood		12-20-40
					9+98.5	9+95.5		# 1533		2025R Hood		4-25-02
10+0	122.40	114.28	8.12		10+25.3	10+22.3		# 877		2032 Hood		9-10-48
					10+49.5	10+46.5						
					10+73.6	10+70.6		# 2968	# 560	2040 Hood		8-29-46
					10+97.0	10+94.0						
11+0	122.60	114.38	8.22		11+19.7	11+11.7		# 1899	# 1188	2044 Hood		10-12-39
				11+25.8	11+48.8	11+45.8				2045 Hood		10-14-38
					11+74.0	11+71.0						
					11+98.5	11+95.5						
12+0	122.70	114.48	8.22		12+26.2	12+23.2		# 1107		2057 Hood		9-27-38
					12+49.7	12+46.7		# 3169	# 909	2056 Hood		3-5-41
					12+70.8	12+67.8						
13+0	123.10	113.91 (M.H.E # W)		13+79.5	13+00.5	12+97.5						

2001-00450- 3/1/01- 1917 N Hood - Ks Ditching- 4" SCH 40- 17WINCO, 2H45, Replace 20' & repair broken pipe by house

1999-00545- 8/30/99- 1948 N Garland- McClung's- 4" SCH 40- 4" CITY TAP- PREDCO 158' SOF MIT 6176(518) Fernco- 17WINCO- 2045

76-7337
 55198
 Repair #3022-Tap-1918-20-28-22 W 18th-110-50-Carter-6" Line
 #5321 #3059-Tap-2059 Hood-2-9-50-Reynolds-(12+05.5)-2051 7th @ 121301 Redd. Root. 3 Fernco, 2 twin co, 1 WYE, 1 H22, 2 KICKOUTS, 4" 40 PVC