



Laura Ave.								
18	16	14	12	10	8	6	4	2
2348	2347	2334	2330	2324	2318	2314	2308	2302
			2+87.6	8" Line				
17	15	13	11	9	7	5	3	1
2341	2341	2335	2331	2325	2321	2315	2309	2303
Ave. St.								

Pattie Ave.								
18	16	14	12	10	8	6	4	2
2348	2347	2334	2330	2324	2318	2314	2308	2302
			2+91.3	8" Line				
17	15	13	11	9	7	5	3	1
2351	2345	2329	2323	2327	2321	2315	2309	2303
Lulu Ave. Blake Ave.								

240 ft
S. Pattie
(2308-2314 ft)

LAT. L - DIST. B - S.S. # 20
W. B. CARTER - 1941

D-233

CONSTRUCTION RECORD							SERVICE RECORD					
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	96.50	88.0	8.5	0+0								
					0+66.8	0+69.8	# 930	# 1785	2348 Laura	2347 Pattie	2-2-42	5-11-42
1+0	98.7	88.1	10.6		1+30.8	1+23.8	# 961	# 82	2342 Laura	2341 Pattie	2-4-42	9-12-41
					1+90.4	1+87.4	# 962	# 83	2334 Laura	2333 Pattie	2-4-42	9-12-41
2+0	99.0	88.2	10.8		2+16.3	2+13.3	# 1001		2330 Laura		2-7-42	
						2+54.0		# 84		2331 Pattie		9-12-41
					2+76.3	2+73.3	# 1002		2324 Laura		2-7-42	
				2+87.6								
					2+98.8	2+95.8		# 85		2325 Pattie		9-12-41
3+0	99.5	88.3	11.2		3+30.0	3+27.0	# 1003		2318 Laura		2-7-42	
					3+56.8	3+53.8		# 86		2321 Pattie		9-12-41
					3+85.2	3+82.2	# 1004		2312 Laura		2-7-42	
4+0	99.5	88.4	11.1		4+12.3	4+09.3		# 1005	2308 Laura		2-7-42	
					4+39.8	4+36.8						
					4+67.4	4+64.4						
					4+93.0	4+90.0	# 1006	# 80	2302 Laura	2309 Pattie	2-7-42	9-12-41
5+0	99.8	88.5	11.3		5+20.8	5+17.8		# 170		2303 Pattie		3-13-42
					5+47.0	5+44.0						
	99.9	88.58	11.32	5+80								
0+0	96.5	88.0	8.5	0+0		MH Jap						
					0+74.0	0+71.0	# 1786	# 2361	2349 Pattie	2350 Lulu	5-11-42	11-1-74 12-12-65
1+0	98.4	88.1	10.3		1+01.9	0+98.9						
					1+27.7	1+24.7	# 551	# 552	2342 Pattie	2345 Lulu	11-10-41	11-10-41
					1+57.7	1+54.7						
					1+83.9	1+80.9	# 549	# 550	2334 Pattie	2339 Lulu	11-10-41	11-10-41
2+0	98.5	88.2	10.3		2+11.3	2+08.3						
					2+39.4	2+36.4	# 3498	# 461	2330 Pattie	2335 Lulu	7-16-41	10-20-41
					2+66.0	2+63.0						
3+0	98.8	88.3	10.5	2+91.3	3+00.1	2+97.1	# 547	# 548	2324 Pattie	2327 Lulu	11-10-41	11-10-41
					3+24.6	3+21.6						
					3+52.0	3+52.0	# 339	# 338	2318 Pattie	2321 Lulu	1-6-41	10-13-41
					3+82.3	3+79.3						
4+0	99.1	88.4	10.7		4+10.0	4+07.0						
					4+34.3	4+31.3	# 324	# 337	2314 Pattie	2315 Lulu	10-11-41	10-13-41
					4+62.7	4+62.7	# 323	# 336	2308 Pattie	2309 Lulu	10-11-41	10-13-41
					4+97.8	4+94.8						
5+0	99.5	88.5	11		5+26.8	5+23.8	# 1171	# 1172	2302 Pattie	2303 Lulu	3-13-42	3-13-42
					5+55.9	5+52.9						
	99.6	88.58	11.02	5+81.0								

2004-00048-11/04- 2318 S Pattie - Clearwater Exc - City wye repair (on msmt above) 4" Freeco - 4" PVC, 2 dir co, 1122, 1022
 fell replacement from house to main

87 - top - 2315 Pattie - 9-12-41 - Frederick Pkg.