

D-236

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	97.80	87.84	9.96	0+0	0+59.0	0+56.0						
1+0	99.00	87.94	10.96		0+84.9	0+81.9	#14130	#1596	2356	2355	5-16-69	4-24-42
					1+20.2	1+17.2	#14131	#1740	1da	Laura	5-16-69	5-7-42
					1+45.5	1+42.5	#1737	#1740	1da	Laura	5-7-42	5-7-42
2+0	99.00	88.04	10.96		1+70.4	1+67.4	#1738	#1610	2348	2347	5-7-42	4-29-42
					1+97.5	1+94.5			1da	Laura		
					2+21.0	2+18.0	#1739	#1741	2342	2341	5-7-42	5-7-42
3+0	99.70	88.14	11.56	3+30.4	2+46.1	2+43.1	#1739	#1741	1da	Laura	5-7-42	5-7-42
					2+71.0	2+68.0	#2082	#2091	2340	2339	6-16-42	6-16-42
					2+95.6	2+92.6	#2496	#2496	1da	Laura	8-7-42	
4+0	99.70	88.24	11.46		3+22.1	3+19.1	#2083	#2083	2333	Laura	6-16-42	
					3+47.0	3+44.0	#2066	#2066	2328	1da	8-3-42	
					3+71.0	3+68.0	#2128	#2128	2327	Laura	7-1-42	
5+0	100.00	88.34	11.66		3+94.3	3+91.3	#2665	#2665	2322	1da	9-9-42	
					4+21.8	4+18.8	#2045	#2045	2321	Laura	6-3-42	
					4+43.4	4+40.4	#2718	#4920	2318	2317	9-23-42	4-22-53
6+0	99.80	88.44	11.36	6+60.7	4+70.0	4+67.0	#2710	#2710	2312	1da	9-22-42	
					4+96.5	4+93.5	#2710	#2710	2311	Laura	6-6-49	
					5+19.8	5+16.8	#2717	#2718	2308	2307	9-23-42	9-23-42
7+0	99.60	88.54	11.06		5+46.8	5+43.8	#2717	#2718	1da	Laura	9-23-42	9-23-42
					5+71.5	5+68.5	#2715	#2716	2302	2301	9-23-42	9-23-42
					5+97.4	5+94.4	#2715	#2716	1da	Laura		
8+0	100.10	88.64	11.46		6+23.9	6+20.9	#2715	#2716	2258	2257	5-28-62	6-3-51
					6+45.2	6+42.2	#1609	#1712	2253	2253	Laura	7-24-50
					7+31.9	7+28.9	#2658	#2658	2247	2247	Laura	11-20-49
9+0	99.70	88.74	10.96		8+06.7	8+03.7	#4276	#2999	2248	2247	4-4-51	1-9-50
					8+32.5	8+29.5	#1288	#1288	2240	1da	8-19-49	
					8+56.3	8+53.3	#1560	#1560	2238	1da	4-20-42	
10+0	99.60	88.84	9.76	9+91.1	8+80.5	8+77.5	#1560	#1560	2234	1da	11-22-49	
					9+104.6	9+101.6	#2550	#2550	2230	1da	5-24-52	
					9+34.8	9+31.8	#1379	#1379	2233	Laura	8-13-46	
11+0	99.70	88.94	9.76		10+02.4	10+02.4	#4028	#1763	2222	1da	9-28-51	8-16-54
					10+31.7	10+28.7	#1763	#1763	2221	Laura	8-18-53	
					10+56.5	10+53.5	#3973	#3973	2225	Laura	2-28-51	
12+0	100.10	90.04	9.96		11+04.9	11+01.9	#1559	#1559	2226	1da	4-20-42	
					11+29.2	11+26.2	#21708	#21708	2207	Laura	10/31/28	6-13-51
					11+56.0	11+53.0	#2554	#4970	2207	11252	6-13-51	6-13-51
13+0	100.20	90.14	10.06	13+20.5	12+04.4	12+01.4	#72815	#2553	2205	1da	11-22-29	
					12+29.4	12+26.4	#2553	#2553	2205	1da		
					12+55.4	12+52.4	#2553	#2553	2205	1da		

#6708-Top-2239 Laura-12-4-51-McDonald (9+41)
 #6612-Top-2348 1da-11-26-51-R. La Fay
 #1199-Top-2344 1/2 1da-6-16-54-Frederick Pibg.
 top C30802-2221 Laura-3-3-72 George Cherry (10+13 L)
 23117-2237 J. Ida-5-10-89-repair - Bob Dent