



LAT. A , DIST. E , S. S.#21
W. B. CARTER , 1941

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	104.8	98.50	5.30	0+0	0+68.7	0+65.7	#2301	#413	1336 S. Millwood	1337 S. Fern	8-10-42	7-13-77 10-16-41
1+0	104.2	98.60	5.60		0+97.3	0+94.3	#420	#419	1332 S. Millwood	1333 S. Fern	10-16-41	10-16-41
2+0	103.9	98.70	5.20		1+25.2	1+22.2	#326	#327	1328 S. Millwood	1329 S. Fern	10-13-41	10-13-41
					1+55.6	1+52.6	#421	#2504	1324 S. Millwood	1325 S. Fern	10-16-41	8-10-42
					1+85.7	1+82.7		#427		1321 S. Fern		10-16-41
				3+23.2	2+19.9	2+16.9						
					2+52.7	2+46.7	#222	#2502	1320 S. Millwood	1321 S. Fern	10-16-41	
					2+78.0	2+75.0	#2502	#2503	1316 S. Millwood	1317 S. Fern	8-16-42	8-10-42
					3+04.9	3+01.9	#423	#428	1312 S. Millwood	1313 S. Fern	10-16-41	10-16-41
4+0	104.1	98.90	5.20		3+38.8	3+35.8	#424	#429	1308 S. Millwood	1309 S. Fern	10-16-41	10-16-41
					3+66.1	3+63.1	#425	#430	1304 S. Millwood	1305 S. Fern	10-16-41	10-16-41
5+0	104.3	99.00	5.30		3+95.0	3+92.0	#431	#436	1300 S. Millwood	1301 S. Fern	8-21-42	10-16-41
6+0	104.8	99.10	5.70		4+21.8	4+24.8						
					4+61.4	4+58.4						
					4+86.1	4+83.1						
					5+17.1	5+14.1						
					5+44.2	5+41.2						
					5+77.9	5+74.9						
					6+08.0	6+05.0						
					6+20.9	6+23.9						
	104.4	99.15	5.25	6+45.1								
0+0	104.3	99.0	5.3	0+0	0+55.7	0+65.5	#00875		1356 S. Glenn		7-24-50	
1+0	104.4	99.1	5.30		0+81.0	0+96.8	#274		1352 S. Glenn		1-23-51	
					1+08.8	1+21.8	#272		1348 S. Glenn		1-4-50	
					1+30.8	1+47.3	#290		1333 S. Vine		5-10-50	1-6-03
					1+56.9	1+79.0	#290		1329 S. Vine			10-3-41
2+0	104.2	99.2	5.00	2+14.6	1+82.0	1+79.0	#271		1325 S. Vine		12-9-54	
					2+06.0	2+00.0						
					2+32.5	2+25.6	#269		1321 S. Vine		1-10-05	
					2+58.4	2+44.0	#268		1317 S. Vine		5-15-51	10-3-41
					2+87.5	2+78.5	#2319		1313 S. Vine		3-10-57	
3+0	105.3	99.3	6.00		3+09.3	3+06.3	#3922		1309 S. Vine		2-25-51	10-5-41
					3+34.8	3+37.8	#249		1305 S. Vine		2-24-51	
					3+62.6	3+71.6			1301 S. Vine			9-30-41
					3+90.2	3+96.2						
4+0	104.8	9.94	5.40	4+28.3	4+12.7	4+21.7	4038		1300 S. Glenn		3-9-57	
					4+38.4	4+55.1	#2318		1218 M ¹⁰⁰ Glenn		5-24-93	
					4+64.1	4+96.4	#248		1313 S. Vine		2-26-90	7-15-42
					4+88.4	4+96.4	#1865		1309 S. Vine		7-8-87	9-30-41
5+0	106.0	99.5	6.50		5+12.5	5+21.5	#4565		1312 S. Glenn		5-5-51	
					5+36.7	5+57.6	#4566		1312 S. Glenn		5-5-51	
					5+60.7	5+87.2	#4593		1305 S. Vine			9-30-41
					5+84.2	5+87.2	#2317		1301 S. Vine		5-8-59	
6+0	106.6	99.6	7.00		6+10.6	6+13.6			1300 S. Glenn		10-3-50	7-15-42
					6+30.3	6+37.3					12/29/03	
	106.7	99.65	7.05	6+47.0								

1999-00178- 7/13/99-1337 S Fern-Alt Henning-4" SCH40 -4" W4E (on msmt) Replaced 3' section of @ house, incl co. Replaced 3' section of line 10' from house. Replaced 10' section of line incl connection to main 1H22
 #3090- Tap-1989 Estimer 26 229-57- Kendall Plbg. Co.