



CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	106.7	97.70	9.00	0+0								
1+0	106.8	97.80	9.00									
2+0	106.7	97.90	8.80									
3+0	106.0	98.00	8.00	3+79.8								
4+0	105.6	98.82	6.78		4+11.0	4+08.0			1202 S. Vine			
					4+33.7	4+30.7	#3202				1-16-51	
					4+57.5	4+54.5		C10451	1207 S. Millwood			9-12-68
					4+85.2	4+82.4	#2906	R-2497	1205 S. Millwood			6-12-67
5+0	105.4	98.92	6.48		5+11.3	5+08.3		2673	1211 S. Millwood			2-8-46
					5+33.3	5+30.3		7402				6-27-50
					5+59.1	5+56.1	#2905		1214 S. Vine			10-30-50
					5+86.3	5+83.3			1217 S. Millwood			10-30-50
6+0	105.6	99.02	6.58		6+09.4	6+06.4	#3301		1220 S. Vine	see below		12-8-50
					6+34.2	6+31.2	#3302	2904	1226 S. Vine	1227 S. Millwood		1-3-51
					6+59.0	6+56.0						10-30-50
					6+82.1	6+79.1	#6909	#1352	1719 Walker	1710 S. Walker		12-26-51
7+0	105.4	99.12	6.28		7+07.3	7+04.3						8-24-49
					7+34.6	7+31.6	#2980			1231 S. Millwood		
				7+43.7								12-17-54
				7+93.0								
8+0	105.1	99.23	5.87		8+03.0	8+00.0	#3009		1717 Walker			12-22-54
					8+30.0	8+27.0						8-8-75
					8+54.5	8+51.5				1305 S. Millwood		
					8+79.2	8+76.2						7-23-33
9+0	105.2	99.32	5.88		9+03.1	9+00.1						5-31-68
					9+27.7	9+24.7				1311 S. Millwood		
					9+52.2	9+49.2	#3008					12-22-54
					9+77.6	9+74.6	#6098		1319 S. Vine			10-11-57
				9+90.1								
10+0	105.1	99.42	5.68		10+04.0	10+01.0						
					10+29.4	10+26.4	7602		1322 S. Vine			3-11-83
					10+53.7	10+50.7	12821	#6198	1326 S. Vine			5-20-60
					10+78.2	10+75.2	9490		1326 S. Vine			1-10-84
11+0	104.9	99.52	5.38		11+03.2	11+00.2	2005-2014		1522 R. Vine			11-19-02
					11+29.5	11+26.5	41677	#5691	1719 W. Vine	1331 R. Millwood		
					11+54.2	11+51.2	051081	1759	1719 W. Vine	1325 S. Millwood		
					11+79.1	11+76.1		60528	1327 S. Millwood			8-28-75
				11+88.0								7-25-50
												3-28-77
0+0	105.7	98.80	6.90	0+00	0+40.9	0+37.9	#3974		1130 S. Vine			2-28-51
					0+65.4	0+62.4	#4435	#2920	1125 S. Millwood			
					0+93.5	0+90.5		#5493	1121 S. Millwood			4-24-51
1+0	106.0	98.90	7.10		1+17.2	1+14.2	#2973		1122 S. Vine			6-9-53
					1+41.5	1+38.5		#221	1115 S. Millwood			11-3-50
					1+65.8	1+62.8	#01544		1117 S. Millwood			3-27-50
					1+93.6	1+90.6	1340		S. Millwood			7-5-50
2+0	106.2	99.00	7.20		2+14.8	2+11.8						
					2+42.9	2+39.2	#145		1109 S. Vine			3-16-50
					2+66.7	2+63.7						
					2+91.6	2+88.6	#521		1109 S. Millwood			11-5-41
3+0	106.0	99.10	6.90		3+14.8	3+11.8	#2290		1102 S. Vine			5-10-48
					3+43.4	3+40.4		#1894	1003 S. Millwood			5-19-42
				3+51.1								

2001-00017 - 4/3/01 - 1223 S. Hillwood - Reddy Footr. 4" sch 40 - Replaced all but lower 6' of SWR. No alley cut. 1 TWIN CO, no bends

96-166647 10896 1319 S. Millwood - Bammes Plbg & Sewer

Top #7685 - 1203 S. Millwood - 7-25-44 Tess Hanna

#1057 Top - 1115 1/2 S. Millwood - 4-30-52 - Howard Shepherd

2001-00451 #3015 Top - 1725 Walker - 12-23-51 - The Jones Ply

#295 - Top - 1233 Vine - 3/10/50 - Bauers Ply.

3101 - Wichita Exc - 4" sch 40 Replace all but lower 3' - 2H22, exist co @ house, dirt alley cut