



LAT. 7, DIST. 6, S. S. # 12
 W. B. CARTER 1946

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	8.3	127.82	10.57	0+0	Riser 0+80.2 +80.2	Riser 0+54.5 +77.2	#581	#570	802 S. Vassar	803-5 Clifton	802 S. Vassar	8-29-46
1+0	2.4	127.92	14.91		Riser 4" sch 40 1+12.4 +38.2 +67.0 +95.5	Riser 4" sch 40 1+09.4 +35.2 +64.0 +92.5	1999-00186 #582	2000-01272 #571	810 S. R. Vassar	807 S. R. Clifton	See Below 8-29-46	5-23-01 8-29-46
2+0	2.6	128.02	15.58		Repl 10' Lin. w/ Riser 2+21.0 +44.0 2+75.0	Riser 2+18.0 +41.0 Riser +78.0 +98.0	#35360 #584	#573	818 S. Vassar	819 S. Clifton	10-12-91 ?	8-29-46
3+0	0.7	128.12	13.47		3+01.0 Riser +30.0 +55.4 +84.5	Riser 3+27.0 +52.4 Riser +81.5	#586	#575	830 S. Vassar	829 S. Clifton	830 S. Vassar	8-29-46
4+0	7.9	128.22	10.83		4+10.1 Riser +37.4 +63.1 +93.5	Riser 4+07.1 +34.4 Riser +60.1 +90.5	#669	#577	840 S. Vassar	841 S. Clifton	840 S. Vassar	9-16-46 8-29-46
5+0	5.4	128.32	8.13		5+20.2 Riser +51.3 +77.0	Riser 5+17.2 +48.3 +74.0	#589	#579	852 S. Vassar	851 S. Clifton	852 S. Vassar	8-29-46 9-16-59
6+0	7.8	128.42	10.42		Riser 6+09.8 +19.5	Riser 6+01.8 +16.5	58159 #590	#590	856 S. Vassar	857 S. Clifton	856 S. Vassar	10-14-76 8-29-46
6+23	8.0	128.45	9.92	6+23.0								9-16-59

2001-01272-5/23/01-807 S Clifton- Richardson Pkg- 4" sch 40 - 1 1-way co, 2 TWIN CO, 4 H22, 2 KICKOUTS, Fernco to clay / 1-Fernco to CE at house (DL)
 2000-00625-3/8/00-807 S Clifton- Wichita EXC- 4" sch 40 1 TWIN CO - 1 H45- 1 Fernco (CO RISER ONLY)
 1999-00186 - 7/14/99- 810 S Vassar- Reddi Roofr- 4" sch 40 - Repair sewer 90 on riser- Dirt Alley Cut - 2V22

do sewer 2000-01057 5/3/00 835 S Clifton- 4" sch 40 PVC 4" clo @ house - Even temp