

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
Line #1 0+0	99.8	87.78	12.36	0+0 (OLD M.H.)								
1+0	99.7	87.88	12.41		0+76.6	0+78.6	#1274	#1272	2266 Laura	2265 Patricia	12-12-47	12-12-47
1+09.6	99.7	87.89	12.72	1+09.6 M.H.								
Line #2 0+0	99.1	88.77	11.14	0+0 (OLD M.H.)								
1+0	100.1	88.87	11.88		0+76.8	0+74.0	#1273	#1275	2266 Patricia	2265 Lulu	12-12-47	12-12-47
1+09.1	100.2	88.88	11.99	1+09.1 M.H.								
Line #3 0+0	98.5	87.55	11.69	0+0 (OLD M.H.)								
1+0	98.2	87.65	11.10		0+74.5	0+77.5	#1276	#1278	2266 Lulu	2265 Ellen	12-12-47	12-12-47
1+09.1	98.2	87.66	11.34	1+09.1 M.H.								
Line #4 0+0	97.43	87.17	11.31	0+0 (OLD M.H.)								
1+0	98.4	87.27	11.81		0+74.3		#1277		2266 Ellen B		12-12-47	
1+09.6	98.3	87.28	11.84	1+09.6 M.H.								

#2203-24-2267 Victoria - 3-16-49 - C.L. Brodie

SERVICE RECORD

CONSTRUCTION RECORD

THE FOLLOWING MEASUREMENT ARE THE NEW
REVISED COMPLETE SET OF Y'S & MANHOLE MEASUREMENTS.
REVISED. 10-26-48