



CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	190.2	178.51	11.99	0+0 (old MH)								
0+59.8	189.9	183.33E 178.63S.	6.09 10.79	0+59.8								
1+0	191.2	183.41	7.56									
2+0	191.4	183.61	8.29									
3+0	194.4	183.81	11.39									
3+91.3	197.6	186.00		3+91.3								
4+0	197.8	186.01	12.05									
					+21.5				902 N Belmont		3-24-47	
					4+46.9	+55.7	#1510	#1912	902 N Belmont	901 Crestway	11-15-48	3-31-48
					+76.4		#1511		908 N Belmont		11-15-48	
5+0	196.8	186.11	11.19									
						+6.8	#1813	#1911	910 N R Belmont	905 Crestway	4-13-47	3-31-48
					5+24.7		#1512				11-15-48	
						+46.7 R		#1913		915 Crestway		3-31-48
							#1515		922 N Belmont		11-15-48	
6+0	196.7	186.21	10.94									
					6+24.1		#1516		926 N Belmont		11-15-48	
						4" PVC 40 6+30.1		#1514	9564577	923 Crestway R		5-4-45 3-31-48
							#1517	#1915	930 N Belmont	927 N Crestway	11-15-48	3-31-48
7+0	196.8	186.31	10.89	6+96.4								
						+26.7	#1518		938 N Belmont		11-15-48	
								#1916		933 Crestway		3-31-48
					7+75.3	+78.3	#1519	#1429	942 N Belmont	939 N Crestway	11-15-48	11-5-48
8+0	196.9	186.41	10.62									
					4" SDR 35 8+26.0	+29.0	95-3290-7		948 N R Belmont		3-18-45	
							1582		952 N R Belmont		11-22-48	
					8+74.7	+77.7	92-3934-7				3-18-42	
							1583				11-22-48	
9+0	196.7	186.51	10.40									
					9+25.4	+28.4	#1584	#1987	958 N Belmont	949 N Crestway	11-22-48	2-23-49
					9+74.70k	+77.7	92-3934-7	#2156	952 N Belmont	953 N Crestway	11-22-48	3-14-49
9+95	196.2	186.61	10.05	9+95.0								

Inf. #1535 - 943 N, Crestway - 11-17-48 - Callison P.lly. Co.