



**LAT. 9, DIST. 13, S. S. 12**  
 BUILDERS CONST. INC., NOV. 9, 1955  
 BK. NO. K-33, PROJ. NO. C25-50

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
16+0	96.9	92.20	4.7	16+61.5	16+21.0	16+18.0	#3440	#3448	2902 S. Glenn	2921 S. Glenn	1-30-01 2-15-55	12-30-96 2-15-55	
	97.0	92.32 out 92.42 in	4.7 4.6		16+78.0	16+75.0	#3449	#3454	2828 S. Glenn	2915 S. Vine R	2-15-55	2-15-55	
17+0	97.3	92.50	4.8	17+92.0	17+41.0	17+62.0	#3450	#3455	2832 S. R. Glenn	2907 S. Vine	5-15-57 2-15-55	2-15-55	
					17+92.0	18+49.5	#3451	#3456	2826 S. Glenn	2901 S. Vine	2-15-55	2-15-55	
18+0	97.4	92.70	4.7	18+61.0	18+61.0	18+49.5	#3452	#3456	2820 S. Glenn	2901 S. Vine	2-15-55	2-15-55	
					19+16.5	19+16.5	#3453	#3453	2814 S. Glenn	2-15-55	2-15-55		
19+0	97.6	92.90	4.7	19+73.5	19+16.5	19+16.5	#3453	#3453	2814 S. Glenn	2-15-55	2-15-55	2-15-55	
					97.9	93.04 out 93.14 in	4.9 4.8	NORTH SOUTH	20+15.0	20+36.0	#3460	#3465	1807 W. 27th St.
20+0	97.6	93.20	4.4	20+79.0	20+15.0	20+36.0	#3461	#3465	1801 W. 27th St.	1725 Regal	2-15-55	2-15-55	
					21+35.5	21+73.0	#3462	#3466	1721 W. 27th St.	1722 Regal	2-15-55	10-28-96 2-15-55	2-15-55
22+0	97.2	93.60	3.6	22+63.0	22+63.0	22+60.0	#3469	#3467	1715 W. 27th St.	1716 Regal	2-15-55	2-15-55	
					97.8	93.78 out 93.88 in	4.0 3.9	EAST	23+15.0	23+67.5	#3470	#3471	2815 S. Millwood
23+0	97.5	93.91	3.6	23+81.5	23+15.0	23+67.5	#3470	#3471	2815 S. Millwood	2821 S. R. Millwood	2-15-55	7-1-96 2-13-55	
					97.9	94.07	3.8	SOUTH	0+21.5	0+66.0	#3299	#3400	1820 W. 30th St.
0+0	95.8	89.62	6.2	0+78.5	0+21.5	0+66.0	#3299	#3400	1820 W. 30th St.	1826 W. 30th St.	2-15-55	2-15-55	
0+0	97.9	93.15	4.7	0+73.5	NORTH SOUTH	0+18.0	0+15.0	#3452	#3457	1815 W. 27th St.	2809 S. Glenn	2-15-55	2-15-55
					98.0	93.45	4.5	(4" stub N.W.)	0+73.5	0+73.5	#3459	#3459	2802 S. Glenn
0+0	97.8	93.88	3.9	0+72	EAST	0+21.5	0+74.5	#3431	#3468	1902 S. 27th St.	2807 S. R. Millwood	12-15-69	9-10-67 2-15-55
					98.1	94.08	4.0	1+00	1+00	#3468	#3468	2807 S. Millwood	2-15-55
0+0	155.5	149.50	6.0	0+28.0	0+25.0	0+87.7	0+84.7	#3187	#3187	2306 S. Voluntary	2315 N. Erie	5-25-53 11-28-56	2-20-58 2-13-56
1+0	159.1	151.70	7.4	1+48.5	1+45.5	1+99.0	1+96.0	#6976	#3772	2344 S. Voluntary	2335 N. Erie	12-5-55	2-10-56
2+0	162.8	153.90	8.9	2+31.4	2+31.4	2+31.4	2+31.4	#492	#492	2335 N. Erie	2-11-56	2-11-56	
1+0	163.6	154.78	8.8	2+39.9	2+39.9	2+39.9	2+39.9	#492	#492	2335 N. Erie	2-11-56	2-11-56	

LINE #3 CONTINUED

LINE #3-A

LINE #3-B

LINE #3-C

CAT. 9, DIST. 13, S. S. #12

Rep-2001-00214-11301-2902 S Glenn St - McClung - 4" SCH 40 4" WYE 18" N of SPL (45' S of MH 16+61.5 [16+16.5])  
Replaced all but clay tile line under patio - 1721 W. 27th St, 1H22

Rep-267459-2808 S Glenn - 7-20-78 - 2" Sch 40 (0+73.5)  
2954 Tap 2314 N Voluntary 11.5 St Smith