



LAT. 24, SUB. 2, S.S. NO. 22

W. B. CARTER CONST. CO. INC., FEB. 15, 1956

BK. NO. K-36, PROJ. NO. C25-88

CONSTRUCTION RECORD

SERVICE RECORD

Line #2

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	100.3	93.40	6.9	0+00 = 1+53.5 in line #1	0+23.5	0+26.5	#5736	#16190 #5735	1445 Rita	1414 Rita	7-26-55	4-29-86 7-26-55
1+0	101.0	93.80	7.2		1+04.5	1+07.5	#6371	#6351	1434 Rita	1438 Rita	9-13-55	9-13-55
2+0	101.9	94.20	7.7		1+71.0	1+74.0	#6370		1433 Rita		9-13-55	
3+0					2+25.0	2+28.0	#5737	#6349	1427 A Rita	1426 Rita	9-13-55	9-13-55
3+0	101.5	94.60	6.9	3+00.7	2+87.6	2+90.6	#5737	#5734	1421 Rita	1420 Rita	7-26-55	7-26-55
4+0	102.0	95.00	7.0		3+51.6	3+54.6	#5738	#5733	1415 B Rita	1414 R Rita	7-26-55	7-26-55
5+0	102.2	95.40	6.8		4+19.7	4+22.7	#6369	#6348	1408 Rita	1406 Rita	9-13-55	9-13-55
6+0	103.4	95.80	7.6	6+00.0	4+75.5	4+78.5	#6367	#6347	1401 Rita	1400 Rita	9-13-55	9-13-55
7+0	103.5	96.20	7.3		5+41.0	5+44.0	#6366	#6346	1339 Rita	1337 Rita	9-13-55	9-13-55
8+0	103.3	96.60	6.7		5+88.0	5+91.0	#5739	#5732	1333 Rita	1332 Rita	7-26-55	7-26-55
9+0	103.3	97.00	6.3		6+46.5	6+49.5	#5740	#5731	1327 Rita	1326 Rita	7-26-55	7-26-55
9+0	103.2	97.04	6.2	9+09.0	7+13.3	7+16.3	#6365	#6345	1321 Rita	1322 Rita	9-13-55	9-13-55
9+0					7+79.5	7+82.5	#6364	#6344	1315 Rita	1314 Rita	9-13-55	9-13-55
9+0					8+32.7	8+35.7	#6363	#6343	1307 Rita	1308 Rita	9-13-55	9-13-55
9+0					8+77.9	8+80.9	#5741	#5742	1301 Rita	1291 Rita	7-26-55	7-26-55
0+0	98.3	89.95	8.4	0+00 Exist'g MH	Y-North	Y-South						
0+03	Req.	Project			0+21.4	0+23.4	#12818	C-51620	1400 Greenfield	1400 W Greenfield	6/19/60	9-30-75
1+0	97.7	90.35	7.3		0+85.5	0+87.5	#11762	C-5967	1405 Greenfield	1410 W Greenfield	9-2-58	12-1-67
2+0	98.4	90.75	7.7		1+42.0	1+47.4	#93-2677	#3582	2739 S Greenfield	1401 Greenfield	10-13-93	1-18-57
3+0	98.2	91.15	7.1	3+00.0	1+59.0							
4+0	98.2	91.55	6.6		2+90.0		8233		1313 Greenfield		10-7-58	
5+0	98.0	91.95	6.0		3+63.2	3+12.8	#11335	#2224	1309 Greenfield	1300 W Greenfield	8-26-59	9-7-56
6+0	98.0	92.35	5.6	5+99.2	4+36.8	4+69.1	#1881	#1233	1305 Greenfield	1300 W Greenfield	11-21-58	8-7-56
7+0	97.9	92.75	5.1		5+07.2	5+18.5	8774	#2226	1301 Greenfield	1300 W Greenfield	11-24-58	9-14-56
8+0	97.9	93.15	4.7		5+80.6	6+06.3		#2227	1301 Greenfield	1300 W Greenfield	11-24-58	19-7-56
9+0	98.6	93.55	5.0	8+99.4	6+51.0	6+64.2	#1358	#2228	1213 Greenfield	1200 W Greenfield	8-22-63	9-7-56
10+0	99.4	93.95	5.4		7+24.0	7+36.0	11682	704	1209 Greenfield	1200 W Greenfield	10-28-59	5-7-56
11+0	99.2	94.35	4.9		7+97.3	8+08.4	7433		1205 Greenfield	1200 W Greenfield	7-18-58	3-14-56
11+0	99.0	94.55	4.4	11+49.5	8+70.2	8+85.0	#1230	#1493	1201 Greenfield	1200 W Greenfield	11-24-58	2-24-56
11+0	99.0	94.55	4.4	11+49.5	9+14.4	9+41.6	18908		1123 Greenfield		8-20-87	
11+0	99.2	94.35	4.9		9+58.8	10+14.5		705	1133 Greenfield		5-7-56	
11+0	99.0	94.55	4.4	11+49.5	10+32.5	10+88.0	95-12229	#11331	1113 R Greenfield	1126 B Greenfield	Repl entire line 2/12/55 = 1145	12-2-99 3-14-54 4-28-88 7-30-57

LAT. 24, SUB. 2, S. S. NO. 22

#2225  
1312 W  
9-7-56

#6350 - 1452 Lydia - Reynard - 9-13-55  
 3647 - 2709 S. Martinsons - 2/29/57  
 6717 Top 1113 Greenfield - 4-27-58  
 8715 - top - 1217 Greenfield - Res. Drifter - 11-24-58 (5+90.2)  
 #18256 - top - 1109 Greenfield - D.A. Smith - 8-25-50 (11+12.5) - Repl from house to garage only  
 9404 - top - 1426 W. 27th - Bradford Alby - 2-27-59 (0+50)