

CONSTRUCTION RECORD

SERVICE RECORD

from PG 61
Cont. Line # 8
Cont. Line # 9
Line # 9A
Line # 9B
Line # 9C
Line # 9D
Line # 9E
Line # 9F
Line # 9G
Line # 9H
Line # 9I on page 62
Line # 9J
Line # 9K

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
15+00	117	107.3	9.7		Clean out							
16+00	119	109.1	9.9	15+43	15+91		10999		2948 S. Davidson		10-21-68	
17+00	119	110.1	8.9		16+34.1		25043		2948 S. Davidson		9-28-67	
18+00	119	110.9	10.0		17+98		46654 (repair)		2940 S. Davidson		9-16-74	
19+00	118	111.9	6.1	M.H. 18+83			22259		3986 Dunham		12-17-70	
Continue on page												
6+00	113	105.7										
7+00	115	107.1										
8+00	117	109.6	7.4	7+39								
9+00	120	112.2	7.8	8+99	8+99							
10+00	120	112.0	6.0		9+69							
11+00	123	117.1	5.9		10+89							
12+00	124	119.0	5.0	11+70								
13+00	127	121.6	5.4	12+90	12+90							
14+00	130	123.6	6.4		13+65							
15+00	134	127.4	4.6	15+00	13+80.0		11352		3072 S. Clifton		7-3-84	
16+00	135	131.5	3.5		16+37							
17+00	140	133.6	6.4		17+15		48040		3126 S. Clifton		1-14-75	
18+00	147	139.8	7.2					96-18797	3624-32 E. Dunham		11-7-96	
0+00	142	133.9	10.1		Existing C.O.							
1+00	139	135.6	3.4	1+65 MH	1+65		70263		3672 E. Dunham		2-13-79	
2+00	138	135.9	2.1	1+90	2+45 (x.c.o.)		92-42847		3133 S. Yale		11-23-92	
0+00	136	130.6	5.4		Existing C.O.							
1+00	141	135.6	5.4					20544	3120 S. Clifton		4-25-88	
0+00	124	129.5	4.5	1+80	1+80 (x.c.o.)							
1+00	132	130.7	1.3	0+72								
2+00	139	131.9	7.1									
0+00	138	134.0	4.0	2+05	2+05		4" sch 40 2+12.0	96-71609	3117 S. Yale	AK# 315	5-14-96	
1+00	138	128.9	9.1	1+90	1+90							
2+00	141	138.4	2.6									
0+00	128	122.9	5.1		2+55 (x.c.o.)							
1+00	128	127.0	1.0		0+70							
0+00	127	121.3	5.7		0+70							
1+00	130	124.1	5.9									
2+00	133	126.9	6.1				97-12237		322 Clifton		7-21-97	
0+00	133	127.5	5.5		2+00							
1+00	128	119.0	5.0	Existing MH								
2+00	131	127.6	3.4									
0+00	122	117.1	4.9		Existing C.O.							
1+00	125	118.8	6.2									
2+00	126	120.5	5.5									
0+00	120	114.0	6.0		Existing C.O.							
1+00	121	116.0	5.0		0+80							
2+00	124	117.0	7.0		1+80							
0+00	120	112.2	7.8		Existing C.O.							
1+00	119	113.0	6.0									

R.C. 61595-3656 Dunham - Alkenning - 6-13-77 (0499.1) 94-9056-7 61364 3040 S. Clifton - 4" PVC 90
 R.C. 64612 3003 S. Clifton - Campbell 12-20-77 (1+05) (0480MH)
 # 1378 10/30/91 3092 S. Clifton John McClung - (Repl 3" pipe in yard with 4" sch 40)
 94-31697 3-10-94 2958 S. Davidson - McClung - wye 16+54 4" sch 40
 98-58301 4/19/88 2952 S. Davidson - Ks Ditching -

2001-03211-12118/01-3640 E Dunham - Samuel Bangle - 4" SCH40 - ITWINCO, LV45 - Tied back to existing Bldg Sew
NO msmt