

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
Line # 8M	0+00	136	129.6	6.4								
	1+00	136	132.4	3.6								
		136	133.7	2.3	1+35	1+35						
Line # 8N	0+00	138	131.0	7.0	Existing MH							
	1+00	137	132.0	5.0								
	2+00	140	133.0	7.0			3+12	C-6-1375	4/11/80	4/11/80	8-12-80	11-10-75
	3+00	141	134.0	7.0				00968				
		141	134.9	6.1	3+40							
	4+00	140	135.0	5.0								
	5+00	140	135.7	4.3								
		140	137.0	3.0		5+45		C76084	4093	4093	1-14-80	
	6+00	140	137.5	2.5		6+00 (r.c.o.)						
Line # 8N-1	0+00	138	137.0	1.0								
	1+00	142	140.0	2.0								
		142	140.0	2.0								
Line # 8P	0+00	154	141.0	13.0	Existing MH							
		157	150.7	6.3		1+10 (r.c.o.)						
	1+00	157	150.8	6.2		0+97						
	2+00	157	151.8	5.2								
		157	152.2	4.8		2+47						
Line # 8P-1	0+00	157	151.5	5.5		Existing (c.o.)						
		160	152.2	7.8	0+70	1+70						
	1+00	159	152.5	6.5								
		159	153.0	6.0		1+60 (r.c.o.)						
Line # 8H	0+00	119	111.99	7.0								
	1+00	119	113.53	5.5								
		121	114.8	5.3								
	2+00	122	114.9	7.3								
	3+00	122	116.4	5.6								
		123	117.1	5.9								
		123	118.0	5.0								
Line # 8G	0+00	118	110.9	7.1								
	1+00	123	113.8	9.2								
		125	115.4	10.1	1+50	1+50						
	2+00	124	116.9	7.1								
		123	119.0	4.0		2+75						
Line # 8F	0+00	115	108.4	6.6								
	1+00	117	111.0	6.0								
		119	112.9	6.1								
	2+00	120	114.1	5.9								
		121	116.5	4.5								

2001-02164- 813061-2992 S Davidson- Padgett Ex- Pipe burst Replacement 4" PE SDAT- CITY REPAIR. 4" PREDCO 10' N OF MH - 1V45, 1V22, 1TWINCO, 3 Fernco
 2000-01956- 2924 S Davidson- 91100-McClung's - 5/0 26' N of Sidewalk (N.S. of SW)
 2000-01957- 2930 S Davidson- 91100-McClung's - 5/0 53' N of Sidewalk (N.S. of SW)

#26388- 10/26/90- 3741 Sunny Brook- Henning (215' W. OR NW MH)