

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North-West	South East	North West	South East	North West	South East	North West	South East
Line#12C1	0+00	127	139.9	7.1								
	1+00	127	141.8	5.2								
	2+00	128	143.7	2.3								
		128	142.0	2.0		2+15						
Line#12C2	0+00	127	138.3	8.7	Existing MH							
	1+00	125	139.0	6.0			1+22		Repair	3178 So. Clifton		7-16-69
		125	139.5	4.5	1+70	1+70						
Line#12C3	0+00	127	139.8	7.2	Existing MH							
	1+00	128	142.2	5.8								
	2+00	150	149.5	5.5		2+00						
Line#12D	0+00	139	130.9	8.1								
	1+00	121	135.5	5.5								
		141	135.5	5.5	1+05	1+05						
Line#12E	0+00	137	129.1	7.9								
	1+00	137	133.5	3.5								
		138	133.5	2.5		1+05						
Line#12F	0+00	133	127.2	5.8	Existing MH							
	1+00	134	128.0	6.0								
		135	128.7	6.3	1+50							
	2+00	135	129.4	5.6								
	3+00	136	130.8	5.2								
		137	131.1	5.9		3+25						
	4+00	138	133.1	2.9								
		120	134.6	5.4	4+55	4+55						
	5+00	121	136.0	2.9								
		142	136.5	5.5		5+30 (X.C.O.)						
Line#12F1	0+00	135	128.8	6.2	Existing MH							
	1+00	137	130.0	6.6								
	2+00	138	132.0	6.0				95129077		3180 R S. Lutak		8-21-25
		139	132.4	6.6	2+70	2+20						
	3+00	141	133.7	7.3								
		142	134.7	6.3	3+63							
	4+00	142	137.2	2.8								
	5+00	143	138.0	5.0								
		143	138.5	2.5		5+38 (C.O.)						
Line#12F2	0+00	142	134.8	7.2	Existing MH	0+66						
	1+00	144	135.3	8.7								
		146	135.7	10.3		1+75						
	2+00	146	138.3	7.7								
	3+00	147	141.8	5.2								
		148	143.5	2.5		3+90 (X.C.O.)						
Line#12F3	0+00	139	132.4	6.6	Existing C.O.							
	1+00	121	135.4	5.6								
		142	136.5	5.5		1+35						
Line#12G	0+00	123	118.96	4.0	Existing MH							
		125	119.5	5.5		0+50						
		127	119.9	7.1		0+95						
Line#12H	0+00	114	103.2	10.8	Existing C.O.							
	1+00	116	107.2	8.8								
		118	111.8	6.2		1+70						
	2+00	120	113.6	6.4								
		122	116.0	6.0		2+20						



u