



### CONSTRUCTION RECORD

### SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+00	153.5	148.00	5.5	Existing M.H.								
2+00	156.5	148.20	8.3				13401		181	OR	4-5-55	
3+00							13045		181	OR	6-27-60	
	158.2 (out)	148.60	9.6	3+01 <sup>6</sup>	4" sch 40 PVC		91-354817		8033 E B		10-17-91	
	(in)	148.69	9.5				C20006		Beaufort		7-8-70	
4+00	158.7	148.90	9.8				+398					
5+00	160.1	149.10	11.0				4+637	90-37707	115 R	Rockwood	3-17-97	
							+545	90.73			1-28-59	
6+00	161.7	149.30	12.4				S+758	6554	8025 E		4-9-58	
	162.1	149.39	12.7 (out)				lot 36°	4754	121 S	Rockwood	7-1-63	
	149.49	12.6 (in)	6+477				lot 90°					
7+00	161.6	149.60	12.0				lot 9+56.2	899-454	8025 E	127 R	6-17-94	
8+00	160.0	149.80	10.2					8202	Douglas	Rockwood	10-1-58	
9+00	158.6	150.00	8.6					038549			4-27-73	
10+00	159.2	150.20 (out)	9.0	10+02 <sup>6</sup>	4" stub se. "Y" South							
	151.00 (in)	8.2						6174	145 S	1108 R	2-29-58	
11+00	159.6	152.20	7.4					2000-00551	Rockwood		3-1-52	
								9492			11-6-58	
12+00	161.7	153.40	8.3									
13+00	163.5	154.60 (out)	8.9	13+02 <sup>1</sup>								
	155.60 (in)	7.9										
14+00	165.4	157.40	8.0									
15+00	167.0	159.20	7.8									
	168.4	161.18	7.2	16+12 <sup>5</sup>								

#### PRIVATE CONTRACT

0+00	95.8	89.40	6.4	Existing M.H.
0+60	95.2	90.00	5.2	0+60

\* Set 2005 - 200 S Rock - ORIS Bldg. unreded + New jaw burner Rest. to be built. Wh. will pipe burst thru exit 6" clay line as it crosses 214 Rock. (in PRWASMT) need new means since ORIS tap means is working rest.

2001-02796 115101 8008 E Lynwood - AE Henning - 4" sch 40 - exist tap - Replaced entire line - ITWINCO, 11/22, 11/22

#7012 - Bon 8 way - 8025 E Douglas - Kentell Bldg. - 5/22/58 - Set a 6" on 8" eye 6" S.  
 10519 Tap 107 Rockwood Ridge 7-4-59 3767.6