



(Notice)
There is a
Water Problem
in This area
S.P.R. 12-14-77

NOTE: SUBTRACT 1187.4 TO CONVERT TO CITY ELEV.



SCALE 1"=100'

PURCELL UTILITIES CO., INC.

SEE PAGE K-25

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
<i>NOTE: Subtract 1187.4 To Convert to City Elev.</i>												
LAT. 3-13												
0+00	1273.5	out 62.74 in 66.82	9.8 6.7	0+15 = 21+81.5 SUB 3 SWI Exist. "Drop" 0+00	0+89	0+86	C5977		4604 S. Charles			12-4-67
1+00	73.7		6.7		1+38	1+35	#3934		4610 S. Charles			7-14-67
2+00	73.4		6.2		2+11	2+08	C52403 C5632		4616 S. Charles			11-10-75 11-7-67
3+00	73.2		5.8	3+00	2+78	2+75	C10915		4626 S. Charles			10-14-68
4+00	73.1		5.5		3+49	3+46						
					4+14	4+11	#17017		4635 S. Glenn			11-21-69
5+00	73.0		5.2		4+85	4+82	+C24234		4645 S. Glenn			5-10-71
6+00	73.2		5.2	6+00	5+55	5+52						
					6+40	6+37			1802 S. 46th			4-10-70
7+00	73.0		4.8		7+47.5	7+56	24124		4700 S. Charles			10-17-89
8+00	73.0		4.6		7+56	7+53			4700 S. Charles			10-17-89
					8+24	8+21						
9+00	73.0		4.4	9+00	8+94	8+91			4717 S. Glenn			8-5-84
					9+52	9+49						
10+00	72.8		4.0		9+36.6	9+33	*C35753 C72385		4725 S. Glenn			11-2-72 6-18-79
					10+19	10+16			4731 S. Glenn			
11+00	73.0		4.0		10+86	10+83						
					11+56	11+53						
12+00	73.2		4.0		12+11	12+08						
	73.8		4.5	Flush 12+40								
LAT. 3-14												
0+00	72.8	out 64.23 in 66.80	8.6 6.0	0+00-20 = 24+85.9 SUB 3 SWI Exist. "Drop" 0+00	0+74	0+80			4556 S. Clarence			1-14-83
1+00	73.0		6.0		1+14	1+20	7370		4550 S. Clarence			4-11-83
					1+74	1+83	7811		4544 S. Clarence			3-29-83
2+00	73.5		6.3		2+47	2+50	7143		4538 S. Clarence			12-9-82 11-17-82
3+00	73.5		6.1	3+00	3+10	3+10	7016		4526 S. Clarence			10-26-82
4+00	73.4		5.8		3+68	3+71	6849					
					4+14	4+35						
					4+74	4+98						
5+00	73.6		5.8		5+32	5+42	98-94057		4505 S. Clarence			6-2-98
					5+72	5+72	C59610		4501 S. Charles			1-25-77
	73.5		5.5	Flush 6+00								
LAT. 3-15												
0+00	72.8	out 64.23 in 65.92	8.6 6.9	0+20 = 24+85.9 SUB 3 SWI Exist. "Drop" 0+00	0+86	0+83	57051	C10635	4602 S. Clarence	4601 S. Charles	8-4-76	9-24-68
1+00	73.0		6.9		1+25	1+22	C64606	C13423	4607 S. Charles	4607 S. Charles	12-22-77	4-7-69
					1+84	1+81	C65681	C21613	4617 S. Clarence	4615 S. Charles	4-3-78	11-3-70
2+00	73.0		6.7		2+52	2+49		C20957	4627 S. Charles			9-11-70
3+00	72.9		6.4	3+00	3+08.5	3+10	C62896		4626 S. Clarence	4631 S. Charles	9-7-77	12-10-69

Jo. 35748-4725 S. Glenn - 11-2-72 - (9+62.6)
 C52403-4616 S. Charles - 11-10-75 (4+22.1)
 C67075-4446 S. Charles - Repair - 6-26-78 (11+62.4)
 19101-4701 S. Charles - Repair - 9-21-87 - Jess McCullough

K