



LAT. 7, SUB. 12, W. T. S.
 MID-STATES CONST. CO. INC.
 PROJ. NO. C25-18, BK. NO. K-72
 12-22-65

CONSTRUCTION RECORD

SERVICE RECORD

| STATION | ELEVATION | | Depth | MANHOLE | 4-INCH "Y" BRANCHES | | No. of Permit | | House Number | | DATE OF PERMITS | |
|------------------|-----------------------------------|-----------------------------------|-------------------|--------------------------------|--|--|----------------------|-----------------|---|--------------|--------------------------------|------------|
| | Ground | Grade | | | North West | South East | North West | South East | North West | South East | North West | South East |
| LAT 3-15 4+00 | (Note: Sea Level Elev's.) 72.8 | 66.72 | 6.1 | | 3+75 ^o 3+72 ^o | | C64203 | | 4637 S. Charles | | 11-28-77 | |
| | | | | | 4+37 ^o 4+98 ^o | 4+34 ^o 4+95 ^o | C58936 | C13424 C6804 | 4641.50. Charles 4647 S. Charles | | 4-7-69 1-11-2000 12-2-76 | |
| 5+00 | 72.5 | 66.92 | 5.6 | | 5+59 ^o 5+56 ^o | | C24928 | | 4651 S. Charles | | 6-16-71 | |
| 6+00 | 72.0 | 67.12 | 4.9 | 6+00 ^o | ← tap into main 6+39 ^o 6+35 ^o | | C19634 | | 1902 W 46th 1902 W 46th | | 6-9-76 | |
| 7+00 | 72.0 | 67.32 | 4.7 | | 7+15 ^o 7+12 ^o | | C56852 | | | | 7-28-76 | |
| 8+00 | 72.5 | 67.52 | 5.0 | | 8+11 ^o 8+08 ^o | | | | | | | |
| 9+00 | 72.5 | 67.72 | 4.8 | 9+00 ^o | 8+69 ^o 8+64 ^o | | C67366 | | 471 S. Charles | | 9-14-78 | |
| 10+00 | 72.0 | 67.92 | 4.1 | | 9+36 ^o 9+33 ^o 9+97 ^o 9+94 ^o | | | 952387-7 | 472 S. Charles | | 2-21-95 | |
| 11+00 | 72.5 | 68.12 | 4.4 | | 10+56 ^o 10+53 ^o | | C69387 | | 472 S. Charles | | 5-24-79 11-13-78 | |
| 12+00 | 73.0 73.1 | 68.32 68.40 | 4.7 4.7 | | 11+17 ^o 11+14 ^o 11+80 ^o 11+77 ^o 12+25 ^o 12+22 ^o | | | | | | | |
| | | | | 12+40 ^o | | | | | | | | |
| 0+00 | 191.8 193.1 | 184.92 185.14 out 185.24 in | 6.9 8.0 7.9 | 8" V.C.P. 0+54 ^o | | | | | | | | |
| 1+00 | 193.1 | 185.51 | 7.6 | | 0+71 ^o 1+28 ^o 1+49 ^o | | C6212 | | 6850 Farmview 6842 Farmview | | 12-20-67 11-7-66 | |
| 2+00 | 194.2 | 186.11 | 8.1 | | 2+25 ^o | | C2982 | | 6838 Farmview | | 5-5-69 | |
| 3+00 | 195.0 195.6 | 186.65 186.71 | 8.3 8.9 | 2+80 ^o | 3+21 ^o | | C4822 | | 6832 Farmview | | 9-13-69 | |
| 4+00 | 196.5 | 187.31 | 9.2 | | 4+16 ^o | | C2000-00857 C3009 | | 6828 R Farmview | 1145 1145 | 4-6-66 5-9-67 | |
| 5+00 | 198.3 198.4 | 187.91 188.03 | 10.4 10.4 | | 5+02 ^o 5+18 ^o 5+84 ^o | | C7897 | | 6820 Farmview | | 4-17-68 | |
| 6+00 | 199.2 | 188.51 | 10.7 | | 6+54 ^o 7+07 ^o 7+36 ^o | | C2281 | | 6814 Farmview | | 8-30-66 | |
| 7+00 | 198.6 198.2 | 189.11 189.41 | 9.5 8.8 | | 7+48 ^o | | C1817 | | 6808 Farmview 6800 Farmview | | 3-17-67 2-8-67 | |

LAT. 7, SUB. 12, W. I. S.

19101 4701 S. Charles 9-21-87 (4" PVC 40 Inspector shows 75 ft S. of MH replaced from main to house).
2000-00077-4647 S CHARLES 112100 - BOWERS PLB - Soil Pipe Extension - Replaced upper 10' at house.