

CONSTRUCTION RECORD

SERVICE RECORD

Line #1

Line #2

Line #3

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
Lat. 61, Sub. 4, S.S. 23												
0+00	130.2	120.86	9.3	exist. 0+00								
1+00	130.3	121.06	9.2									
	130.6	121.23	9.4	1+84 ⁵								
2+00	130.4	121.26	9.1									
3+00	129.1	121.46	7.6									
	130.6	121.68	8.9	3+61 ⁰								
4+00	129.7	121.83	7.9									
	130.30	121.85	8.4	4+28.4								
					4+38 ⁵							
					4+77 ⁰	4+75 ⁰						
5+00	130.0	122.23	7.8									
					5+26 ⁰	5+29 ⁰						
					5+74 ⁵	5+67 ⁵						
					5+74 ⁵	5+71.4						
					5+77 ⁵							
6+00	130.3	122.63	7.7									
					6+22 ⁵							
7+00	130.4	123.03	7.9									
					6+69 ⁵	6+67 ⁵						
					7+25 ⁵							
					7+43 ⁰							
8+00	130.4	123.43	7.0									
					7+70 ⁰							
					8+04 ⁰							
	130.4	123.60	6.8	8+49 ⁰	4" stub N.							
					8+98 ⁰							
9+00	130.3	123.94	6.4									
	130.7	124.14	6.6	9+49 ⁰	4" stub N. 4" stub N.							
Line #2	0+00	130.4	123.71	6.7	exist. 0+00							
					0+10 ⁵							
					0+78 ⁵	0+67 ⁰						
1+00	130.7	124.11	6.6									
	130.8	124.15	6.7	1+10 ⁰								
Line #3	0+00	130.6	121.78	8.5	exist. 0+00							
					0+18 ⁰	0+16 ⁰						
					0+90 ⁰	0+88 ⁰						
1+00	130.38	122.08	8.3									
					1+74 ⁵	1+72 ⁵						
					1+79 ⁵	1+81 ⁵						
2+00	129.8	122.38	7.4									
					2+19 ⁰							
	129.8	122.47	7.3	2+30 ⁵								
					2+58 ⁰	2+56 ⁰						
					2+91 ⁵	2+89 ⁵						
3+00	129.8	122.68	7.3									
					3+13 ⁵							
					3+45 ⁰	3+43 ⁰						
					3+88 ⁵	3+86 ⁵						
4+00	129.7	122.98	6.7									
	129.5	123.10	6.4	4+35 ⁰	4+28 ⁵	4+26 ⁰						

Sub 2053-00704 10/17/03 3545 N Santa Fe (Hospital of Hope) Maintenance Cont.