



**GENERAL NOTES:**  
 Field Engineer to determine if ground is unstable below line of pipe from Sta. 0+00 to 0+75. If unstable ground condition exists, contractor shall cut to solid ground & install to bottom of pipe with crushed rock. See profile of line of old creek below. Crushed rock shall be 3/4" to 1 1/2" crushed rock. Extra excavation shall be 6" to 12" of special excavation. Replace curb & gutter 5' on Tyler Rd. Replace curb and gutter with asphaltic concrete.

NOTE: CONTRACTOR TO CONTACT OWNERS FOR WYE LOCATION  
 B.M. 137.48 "X" on South curb Rolling Hills Dr. 20' W. of W. End Rd.  
 B.M. 138.33 "STANDARD" @ Tyler & 2nd 28.3' W. & 11.9' S. of & both

Plan Scale 1" = 40'  
 Profile Scale 1" = 40' Vert.

LAT. 11, SUB. 1, WESTLINK S.S.  
 CITY OF WICHITA, KANSAS  
 B. E. SMITH, CITY ENGINEER  
 PROJ. NO. C29-95  
 DATE: Dec. 1969